



Estimated Recalls By Distance

Prepared for

Date: 1/9/2017
ZipCode: 53094



Make	Total	0-5mi	6-10mi	11-15mi	16-20mi	21-25mi
BUICK	721	36	80	74	149	287
CADILLAC	461	18	38	60	104	185
CHEVROLET	7,129	389	730	767	1,546	2,891
GMC	894	38	83	99	194	361
Makes by Distance:		481	931	1,000	1,993	3,724
VIN search requested within a 25 mile radius			TOTAL VINs FOUND:			9,205

ZIP CODE	MAKE	CITY	DISTANCE	Approximate Recall Count
53094	BUICK	WATERTOWN	0	30
53038	BUICK	JOHNSON CREEK	4	6
53036	BUICK	IXONIA	8	5
53098	BUICK	WATERTOWN	9	27
53137	BUICK	HELENVILLE	9	3
53549	BUICK	JEFFERSON	10	21
53178	BUICK	SULLIVAN	10	4
53551	BUICK	LAKE MILLS	10	20
53066	BUICK	OCONOMOWOC	11	53
53594	BUICK	WATERLOO	12	13
53579	BUICK	REESEVILLE	14	3
53059	BUICK	NEOSHO	14	3
53557	BUICK	LOWELL	15	1
53069	BUICK	OKAUCHEE	15	1
53538	BUICK	FORT ATKINSON	16	37
53034	BUICK	HUSTISFORD	16	2
53058	BUICK	NASHOTAH	16	5
53118	BUICK	DOUSMAN	16	11
53039	BUICK	JUNEAU	17	8
53156	BUICK	PALMYRA	18	4
53078	BUICK	RUBICON	18	3
53559	BUICK	MARSHALL	18	10
53018	BUICK	DELAFIELD	18	12
53523	BUICK	CAMBRIDGE	18	12
53531	BUICK	DEERFIELD	19	8
53183	BUICK	WALES	20	4
53029	BUICK	HARTLAND	20	29
53035	BUICK	IRON RIDGE	20	4
53119	BUICK	EAGLE	21	5
53153	BUICK	NORTH PRAIRIE	21	4
53032	BUICK	HORICON	21	10
53925	BUICK	COLUMBUS	22	25
53027	BUICK	HARTFORD	22	42
53190	BUICK	WHITEWATER	23	19
53188	BUICK	WAUKESHA	23	44
53072	BUICK	PEWAUKEE	24	39
53527	BUICK	COTTAGE GROVE	24	18
53916	BUICK	BEAVER DAM	24	53
53089	BUICK	SUSSEX	24	28
53017	BUICK	COLGATE	25	8

ZIP CODE	MAKE	CITY	DISTANCE	Approximate Recall Count
53033	BUICK	HUBERTUS	25	11
53590	BUICK	SUN PRAIRIE	25	76
53094	CADILLAC	WATERTOWN	0	14
53038	CADILLAC	JOHNSON CREEK	4	4
53036	CADILLAC	IXONIA	8	3
53098	CADILLAC	WATERTOWN	9	11
53137	CADILLAC	HELENVILLE	9	2
53549	CADILLAC	JEFFERSON	10	11
53178	CADILLAC	SULLIVAN	10	4
53551	CADILLAC	LAKE MILLS	10	7
53066	CADILLAC	OCONOMOWOC	11	52
53594	CADILLAC	WATERLOO	12	4
53579	CADILLAC	REESEVILLE	14	1
53059	CADILLAC	NEOSHO	14	2
53069	CADILLAC	OKAUCHEE	15	1
53538	CADILLAC	FORT ATKINSON	16	17
53034	CADILLAC	HUSTISFORD	16	1
53058	CADILLAC	NASHOTAH	16	5
53118	CADILLAC	DOUSMAN	16	9
53039	CADILLAC	JUNEAU	17	3
53156	CADILLAC	PALMYRA	18	3
53078	CADILLAC	RUBICON	18	1
53559	CADILLAC	MARSHALL	18	5
53018	CADILLAC	DELAFIELD	18	16
53523	CADILLAC	CAMBRIDGE	18	7
53531	CADILLAC	DEERFIELD	19	4
53183	CADILLAC	WALES	20	4
53029	CADILLAC	HARTLAND	20	28
53035	CADILLAC	IRON RIDGE	20	1
53119	CADILLAC	EAGLE	21	3
53153	CADILLAC	NORTH PRAIRIE	21	3
53032	CADILLAC	HORICON	21	4
53925	CADILLAC	COLUMBUS	22	6
53027	CADILLAC	HARTFORD	22	19
53190	CADILLAC	WHITEWATER	23	13
53188	CADILLAC	WAUKESHA	23	29
53072	CADILLAC	PEWAUKEE	24	53
53527	CADILLAC	COTTAGE GROVE	24	12
53916	CADILLAC	BEAVER DAM	24	19
53089	CADILLAC	SUSSEX	24	24
53017	CADILLAC	COLGATE	25	10
53033	CADILLAC	HUBERTUS	25	7
53590	CADILLAC	SUN PRAIRIE	25	39
53094	CHEVROLET	JOHNSON CREEK	0	1
53094	CHEVROLET	WATERTOWN	0	314
53038	CHEVROLET	JOHNSON CREEK	4	74
53036	CHEVROLET	IXONIA	8	67
53098	CHEVROLET	WATERTOWN	9	226
53137	CHEVROLET	HELENVILLE	9	38
53549	CHEVROLET	JEFFERSON	10	182
53178	CHEVROLET	SULLIVAN	10	55
53047	CHEVROLET	LEBANON	10	1

ZIP CODE	MAKE	CITY	DISTANCE	Approximate Recall Count
53551	CHEVROLET	LAKE MILLS	10	161
53066	CHEVROLET	OCONOMOWOC	11	533
53594	CHEVROLET	WATERLOO	12	128
53003	CHEVROLET	ASHIPPUN	12	3
53016	CHEVROLET	CLYMAN	12	2
53579	CHEVROLET	REESEVILLE	14	41
53059	CHEVROLET	NEOSHO	14	38
53557	CHEVROLET	LOWELL	15	5
53069	CHEVROLET	OKAUCHEE	15	17
53538	CHEVROLET	FORT ATKINSON	16	332
53034	CHEVROLET	HUSTISFORD	16	31
53058	CHEVROLET	NASHOTAH	16	39
53118	CHEVROLET	DOUSMAN	16	121
53039	CHEVROLET	JUNEAU	17	95
53156	CHEVROLET	PALMYRA	18	48
53078	CHEVROLET	RUBICON	18	39
53064	CHEVROLET	NORTH LAKE	18	1
53559	CHEVROLET	MARSHALL	18	118
53018	CHEVROLET	DELAFIELD	18	97
53523	CHEVROLET	CAMBRIDGE	18	115
53531	CHEVROLET	DEERFIELD	19	90
53183	CHEVROLET	WALES	20	49
53029	CHEVROLET	HARTLAND	20	321
53035	CHEVROLET	IRON RIDGE	20	50
53119	CHEVROLET	EAGLE	21	123
53056	CHEVROLET	MERTON	21	1
53153	CHEVROLET	NORTH PRAIRIE	21	45
53127	CHEVROLET	GENESEE DEPOT	21	2
53032	CHEVROLET	HORICON	21	104
53925	CHEVROLET	COLUMBUS	22	195
53027	CHEVROLET	HARTFORD	22	433
53190	CHEVROLET	WHITWATER	23	223
53188	CHEVROLET	WAUKESHA	23	446
53072	CHEVROLET	BROOKFIELD	24	1
53072	CHEVROLET	PEWAUKEE	24	337
53527	CHEVROLET	COTTAGE GROVE	24	197
53916	CHEVROLET	BEAVER DAM	24	476
53089	CHEVROLET	SUSSEX	24	308
53017	CHEVROLET	COLGATE	25	102
53033	CHEVROLET	HUBERTUS	25	103
53590	CHEVROLET	SUN PRAIRIE	25	601
53094	GMC	WATERTOWN	0	31
53038	GMC	JOHNSON CREEK	4	7
53036	GMC	IXONIA	8	8
53098	GMC	WATERTOWN	9	29
53137	GMC	HELENVILLE	9	4
53549	GMC	JEFFERSON	10	20
53178	GMC	SULLIVAN	10	5
53047	GMC	LEBANON	10	1
53551	GMC	LAKE MILLS	10	16
53066	GMC	OCONOMOWOC	11	70
53594	GMC	WATERLOO	12	14

ZIP CODE	MAKE	CITY	DISTANCE	Approximate Recall Count
53579	GMC	REESEVILLE	14	6
53059	GMC	NEOSHO	14	7
53557	GMC	LOWELL	15	1
53069	GMC	OKAUCHEE	15	1
53538	GMC	FORT ATKINSON	16	34
53034	GMC	HUSTISFORD	16	4
53058	GMC	NASHOTAH	16	7
53118	GMC	DOUSMAN	16	16
53039	GMC	JUNEAU	17	10
53156	GMC	PALMYRA	18	5
53078	GMC	RUBICON	18	7
53559	GMC	MARSHALL	18	15
53018	GMC	DELAFIELD	18	14
53523	GMC	CAMBRIDGE	18	11
53531	GMC	DEERFIELD	19	10
53183	GMC	WALES	20	6
53029	GMC	HARTLAND	20	47
53035	GMC	IRON RIDGE	20	8
53119	GMC	EAGLE	21	11
53056	GMC	MERTON	21	1
53153	GMC	NORTH PRAIRIE	21	5
53032	GMC	HORICON	21	11
53925	GMC	COLUMBUS	22	19
53027	GMC	HARTFORD	22	69
53190	GMC	WHITEWATER	23	23
53188	GMC	WAUKESHA	23	42
53072	GMC	PEWAUKEE	24	48
53527	GMC	COTTAGE GROVE	24	29
53916	GMC	BEAVER DAM	24	64
53089	GMC	SUSSEX	24	39
53017	GMC	COLGATE	25	19
53033	GMC	HUBERTUS	25	20
53590	GMC	SUN PRAIRIE	25	80



Recall Summary Report

Date: 01/09/17

Radius: 25

Recall scoring key: 5 = High, 4 = Med, 3 = Low | Recalls excluded: 2 = Remedy not available, 1 = Non-safety related

Total Estimated VINs: 9,205

Make	OEM Code	Overall Score	Risk Score	Profit Score	Reimb. Labor	Labor Estimate	Service Difficulty	Recall Description	Recall Qty (%)
BUICK	16007	5	5	3	\$32	0.3	No Car Lift	Frontal Airbag ad Pretensioner Non Deploy	310 (49.58%)
BUICK	14299	5	4	5	\$212	2.0	No Car Lift	Unintended Ignition Key Rotation (STOP SALE)	64 (10.18%)
BUICK	15757	5	5	1	\$32	0.3	Car Lift	Engine Oil Leak	30 (4.75%)
BUICK	14030	5	5	5	\$191	1.8	Car Lift	Side Impact Airbag Connector (STOP SALE)	10 (1.62%)
BUICK	09047	4	4	2	\$106	1.0	Car Lift	Engine Oil And Exhaust Manifold Fire Hazard	12 (1.89%)
BUICK	14187	4	4	4	\$106	1.0	No Car Lift	Front Safety Belt Anchor (STOP SALE)	11 (1.78%)
BUICK	14271	4	4	4	\$95	0.9	No Car Lift	Power Seat Height Adjuster Bolt	8 (1.32%)
BUICK	12212	4	3	4	\$53	0.5	No Car Lift	Turn Signal Lamp Outage Indicator Not Working	5 (0.75%)
BUICK	14291	3	3	3	\$32	0.3	No Car Lift	Low-beam Headlamps	66 (10.54%)
BUICK	15240	3	3	2	\$127	1.2	Car Lift	Power Liftgate may Fall Prematurely Causing injury - Software Update Required	53 (8.45%)
BUICK	SB13-04-S003A	3	3	2	\$74	0.7	Car Lift	Driver Door Short Circuit	21 (3.32%)
BUICK	15272	3	3	3			Car Lift	Carbon Monoxide Emissions	7 (1.12%)
CADILLAC	16007	5	5	3	\$32	0.3	No Car Lift	Frontal Airbag ad Pretensioner Non Deploy	213 (52.67%)
CADILLAC	14299	5	4	5	\$212	2.0	No Car Lift	Unintended Ignition Key Rotation (STOP SALE)	69 (17.07%)
CADILLAC	15404	5	5	3	\$42	0.4	Programming Only	Automatic Crash Response System	12 (3.07%)
CADILLAC	14457	5	3	5	\$201	1.9	Car Lift	Rear Toe Link Adjuster Lock Nut Torque (STOP SALE)	6 (1.53%)
CADILLAC	14172	4	4	4	\$127	1.2	No Car Lift	Unintended Ignition Key Rotation (STOP SALE)	59 (14.48%)
CADILLAC	09149	4	4	2	\$127	1.2	Car Lift	Front Brake Hose Fitting Corrosion - Replace Front Brake Hoses	5 (1.26%)
CADILLAC	14225	3	3	2	\$148	1.4	Car Lift	Sunroof Drain Hose Leaks	5 (1.23%)
CHEVROLET	14350	5	4	5	\$212	2.0	No Car Lift	Unintended Ignition Key Rotation	764 (12.09%)
CHEVROLET	14299	5	4	5	\$212	2.0	No Car Lift	Unintended Ignition Key Rotation (STOP SALE)	493 (7.8%)
CHEVROLET	16007	5	5	3	\$32	0.3	No Car Lift	Frontal Airbag ad Pretensioner Non Deploy	433 (6.85%)
CHEVROLET	15822	5	5	4	\$74	0.7	No Car Lift	Seatbelt Lap Anchor Tensioner Cable (STOP SALE)	245 (3.87%)
CHEVROLET	15031	5	5	2	\$64	0.6	Car Lift	Safety Belt - Inspect And Repair	223 (3.52%)
CHEVROLET	14152	5	4	5	\$191	1.8	Car Lift	Transmission Shift Cable Fracture	184 (2.91%)
CHEVROLET	14116	5	4	5	\$180	1.7	No Car Lift	Electric Power Steering Assist	116 (1.84%)
CHEVROLET	15757	5	5	1	\$32	0.3	Car Lift	Engine Oil Leak	67 (1.06%)
CHEVROLET	14030	5	5	5	\$191	1.8	Car Lift	Side Impact Airbag Connector (STOP SALE)	45 (0.71%)
CHEVROLET	20760	5	5	1	\$32	0.3	Car Lift	Brake Pedal Pivt Nut/Bolt Loose (STOP SALE)	42 (0.66%)
CHEVROLET	12106	5	4	5	\$180	1.7	No Car Lift	Shift Lever Indicator May Not Display Correct Gear	36 (0.57%)
CHEVROLET	14574	5	5	2	\$85	0.8	Car Lift	Engine Oil Leak On Exhaust Manifold	28 (0.44%)
CHEVROLET	14546	5	5	4	\$95	0.9	No Car Lift	Passenger Airbag Wiring Harness Connector	24 (0.38%)
CHEVROLET	14082	5	5	2	\$95	0.9	Car Lift	Passenger Side Instrument Panel Performance (STOP SALE)	17 (0.27%)
CHEVROLET	02029	5	5	3	\$21	0.2	No Car Lift	Airbag Sensing Diagnostic Module (SDM)	16 (0.26%)
CHEVROLET	10312	5	5	3	\$32	0.3	No Car Lift	Front Safety Belt Anchor Pretensioner Installation	15 (0.23%)
CHEVROLET	27620	5	5	3			Car Lift	Incorrect Trailer Hitch	13 (0.21%)
CHEVROLET	14772	5	5	5	\$170	1.6	No Car Lift	Electric Power Steering Assist may Fail While Driving	13 (0.2%)
CHEVROLET	12190	5	4	5	\$233	2.2	Car Lift	Fuel Odor or Spotting on Ground - Inspect Fuel Pump Module	12 (0.19%)
CHEVROLET	14105	5	5	2	\$138	1.3	Car Lift	Passenger Side Instrument Panel Performance (STOP SALE)	11 (0.18%)
CHEVROLET	14166	5	5	5	\$170	1.6	Car Lift	Seat Mounted Side Impact Airbag Connector	8 (0.12%)
CHEVROLET	31340	5	5	4	\$106	1.0	No Car Lift	Seat Belt Tensioner Cable (STOP SALE)	7 (0.11%)
CHEVROLET	12319	5	5	5	\$753	7.1	Car Lift	Possible Missing Secondary Hood Latch	7 (0.11%)
CHEVROLET	14079	5	5	2	\$117	1.1	Car Lift	Front Axle Right Half Shaft Fracture (STOP SALE)	6 (0.1%)
CHEVROLET	12261	5	5	2	\$64	0.6	Car Lift	Replace Steering Wheel Airbag Coil	6 (0.09%)



Recall Summary Report

Date: 01/09/17

Radius: 25

Recall scoring key: 5 = High, 4 = Med, 3 = Low | Recalls excluded: 2 = Remedy not available, 1 = Non-safety related

Total Estimated VINs: 9,205

Make	OEM Code	Overall Score	Risk Score	Profit Score	Reimb. Labor	Labor Estimate	Service Difficulty	Recall Description	Recall Qty (%)
CHEVROLET	13036	4	4	3	\$42	0.4	No Car Lift	Brake Lamp Malfunction	398 (6.3%)
CHEVROLET	14294	4	4	4	\$117	1.1	No Car Lift	Ignition Key (STOP SALE)	301 (4.76%)
CHEVROLET	14113	4	4	4	\$106	1.0	No Car Lift	Replace Ignition Lock Cylinder and Ignition Key	267 (4.22%)
CHEVROLET	14092	4	4	4	\$74	0.7	No Car Lift	Ignition Switch Replacement	148 (2.34%)
CHEVROLET	13454	4	4	4	\$74	0.7	No Car Lift	Ignition Switch	120 (1.9%)
CHEVROLET	36110	4	4	4	\$106	1.0	No Car Lift	Passenger Seat Occupant Sensing	116 (1.84%)
CHEVROLET	04007	4	3	4	\$53	0.5	No Car Lift	Tailgate Support Cable	106 (1.68%)
CHEVROLET	13146	4	4	4	\$85	0.8	No Car Lift	Low-beam Headlamps inoperative	90 (1.43%)
CHEVROLET	14093	4	4	4	\$106	1.0	No Car Lift	Daytime Running Lamps (DRL) inoperative - DRL Module Overheating	81 (1.28%)
CHEVROLET	14801	4	4	4			Programming Only	Reprogram Engine Control Module	79 (1.25%)
CHEVROLET	14271	4	4	4	\$95	0.9	No Car Lift	Power Seat Height Adjuster Bolt	69 (1.09%)
CHEVROLET	14187	4	4	4	\$106	1.0	No Car Lift	Front Safety Belt Anchor (STOP SALE)	65 (1.03%)
CHEVROLET	09047	4	4	2	\$106	1.0	Car Lift	Engine Oil And Exhaust Manifold Fire Hazard	58 (0.91%)
CHEVROLET	10023	4	4	2	\$64	0.6	Car Lift	Loss of Power Steering Assist - Replace Electric Power Steering Motor	56 (0.88%)
CHEVROLET	14115	4	4	4	\$74	0.7	No Car Lift	Electric Power Steering Assist	53 (0.84%)
CHEVROLET	14203	4	4	2	\$106	1.0	Car Lift	Low-Beam Headlamps Inoperative	49 (0.77%)
CHEVROLET	14133	4	4	4	\$74	0.7	No Car Lift	Replace Ignition Key	40 (0.64%)
CHEVROLET	04002	4	4	4	\$95	0.9	No Car Lift	Ignition Circuit Thermal Events	40 (0.64%)
CHEVROLET	14063	4	4	4	\$74	0.7	No Car Lift	Ignition Switch Replacement	39 (0.61%)
CHEVROLET	10153	4	4	3	\$32	0.3	Programming Only	Heated Windshield Washer Module Short Circuit - Disable and Remove Module	38 (0.6%)
CHEVROLET	05113	4	4	4	\$117	1.1	No Car Lift	Safety Belt Buckle Inoperative	38 (0.6%)
CHEVROLET	05068	4	4	2	\$106	1.0	Car Lift	Front Wheel Speed Sensor Corrosion *Salt States*	36 (0.57%)
CHEVROLET	14417	4	4	1	\$32	0.3	Car Lift	Low Engine Coolant Level without an External Leak	35 (0.55%)
CHEVROLET	09049	4	4	3	\$32	0.3	No Car Lift	Brake Lamps Inoperative *Gulf States*	34 (0.54%)
CHEVROLET	14309	4	4	4	\$74	0.7	No Car Lift	Driver Door Switch Short Circuit	26 (0.41%)
CHEVROLET	02039	4	4	3	\$21	0.2	No Car Lift	Rearward Folding Head Restraints Pinch Point	24 (0.38%)
CHEVROLET	15075	4	3	4	\$64	0.6	No Car Lift	Side Impact Sensor	23 (0.37%)
CHEVROLET	14581	4	3	4			No Car Lift	Carbon Monoxide Emissions	18 (0.29%)
CHEVROLET	04083	4	4	3	\$42	0.4	No Car Lift	Rear Stop/Turn Signal Lamps Inoperative	18 (0.29%)
CHEVROLET	14696	4	4	2	\$117	1.1	Car Lift	Ignition Lock Cylinder Binding	16 (0.26%)
CHEVROLET	04087	4	4	3	\$32	0.3	No Car Lift	Tail Lamps/Stop Lamps	16 (0.26%)
CHEVROLET	06019	4	4	4	\$53	0.5	No Car Lift	Tailgate Support Cable Replacement	16 (0.26%)
CHEVROLET	12213	4	4	4	\$74	0.7	No Car Lift	Brake Vacuum Micro Switch	15 (0.24%)
CHEVROLET	11290	4	3	4	\$53	0.5	No Car Lift	Ignition Coil Spark Plug Boots	15 (0.24%)
CHEVROLET	14456	4	3	4	\$53	0.5	No Car Lift	Secondary Hood Latch Corrosion (STOP SALE)	14 (0.22%)
CHEVROLET	03043	4	4	4	\$53	0.5	No Car Lift	Turn Signals/Hazard Warning Flashers Inoperative	14 (0.22%)
CHEVROLET	08016	4	3	4	\$53	0.5	No Car Lift	Head Impact Protection - Increased Protection	14 (0.22%)
CHEVROLET	00093	4	4	2	\$117	1.1	Car Lift	Front Brake Pipe Contact with Body Cross Sill	14 (0.22%)
CHEVROLET	09184	4	3	4	\$127	1.2	No Car Lift	Material Over Sensing and Diagnostic Module Retaining Moisture	13 (0.21%)
CHEVROLET	05027	4	4	3	\$21	0.2	No Car Lift	Fuel Module Reservoir Assembly	13 (0.21%)
CHEVROLET	14274	4	4	1	\$42	0.4	Car Lift	Liftgate Strut Rod Detaches	13 (0.21%)
CHEVROLET	04110	4	4	3	\$21	0.2	No Car Lift	Right Hand Power Sliding Door Interior Handle	13 (0.2%)
CHEVROLET	14118	4	4	4	\$85	0.8	No Car Lift	Electric Power Steering Assist	11 (0.18%)
CHEVROLET	01073	4	4	4	\$95	0.9	No Car Lift	Stop Lamps/Hazard Lamps Inoperative	10 (0.16%)



Recall Summary Report

Date: 01/09/17

Radius: 25

Recall scoring key: 5 = High, 4 = Med, 3 = Low | Recalls excluded: 2 = Remedy not available, 1 = Non-safety related

Total Estimated VINs: 9,205

Make	OEM Code	Overall Score	Risk Score	Profit Score	Reimb. Labor	Labor Estimate	Service Difficulty	Recall Description	Recall Qty (%)
CHEVROLET	05500	4	3	4	\$64	0.6	No Car Lift	Ignition Distributor System Corrosion-Inspect/Replace	10 (0.16%)
CHEVROLET	15176	4	3	4	\$64	0.6	No Car Lift	Sunroof Switch Compliance	9 (0.15%)
CHEVROLET	14515	4	4	4	\$127	1.2	No Car Lift	Chassis Electronic Control Module Internal Contamination	8 (0.13%)
CHEVROLET	04005	4	4	4	\$53	0.5	No Car Lift	Windshield Wiper Operation	8 (0.13%)
CHEVROLET	05013	4	4	4	\$95	0.9	No Car Lift	Multifunction Switch Contacts	8 (0.13%)
CHEVROLET	SB05-04-S002	4	4	3	\$21	0.2	No Car Lift	Intermittent Incorrect Turn Signal Operation	8 (0.12%)
CHEVROLET	12212	4	3	4	\$53	0.5	No Car Lift	Turn Signal Lamp Outage Indicator Not Working	7 (0.11%)
CHEVROLET	43180	4	4	3			Car Lift	High Pressure Fuel Pump	7 (0.11%)
CHEVROLET	14110	4	4	4	\$106	1.0	No Car Lift	Engine Oil Consumption Due to PCV Valve Wear	6 (0.1%)
CHEVROLET	SR06-09-S002	4	4	3	\$21	0.2	No Car Lift	Brake Lamps Inoperative or Continuous Illumination	6 (0.09%)
CHEVROLET	12081	4	4	4	\$64	0.6	No Car Lift	Oil Spills or Leaks onto Hot Surfaces-Modify Engine Shield	6 (0.09%)
CHEVROLET	14121	4	4	1	\$32	0.3	Car Lift	Transmission Oil Cooler Connection	5 (0.08%)
CHEVROLET	16019	4	4	3			No Car Lift	HVAC Module Temp Door	5 (0.08%)
CHEVROLET	03054	4	4	3	\$32	0.3	No Car Lift	Fuel Pressure Regulator-Replace	5 (0.08%)
CHEVROLET	09226	4	4	2	\$127	1.2	Car Lift	Fuel Odor or Spotting on Ground *Region Specific*	5 (0.08%)
CHEVROLET	14523	4	4	4			Programming Only	Emission Compliance	5 (0.08%)
CHEVROLET	14459	4	4	2	\$127	1.2	Car Lift	Rear Brake Shoe Bonding	5 (0.08%)
CHEVROLET	14730	4	4	2	\$53	0.5	Car Lift	Torque Converter Clutch Wear	5 (0.08%)
CHEVROLET	14192	4	4	3	\$42	0.4	No Car Lift	Unwanted Transfer Case Shift to Neutral	5 (0.08%)
CHEVROLET	15806	4	4	3			Programming Only	Instrument Panel Cluster Odometer Abnormal Increase at Cranking	5 (0.08%)
CHEVROLET	SB13-04-S003A	3	3	2	\$74	0.7	Car Lift	Driver Door Short Circuit	163 (2.57%)
CHEVROLET	17130	3	3	2	\$64	0.6	Car Lift	Key Reminder Chime (STOP SALE)	88 (1.39%)
CHEVROLET	05037	3	3	3	\$21	0.2	No Car Lift	Second Row Center Safety Belt	57 (0.9%)
CHEVROLET	15240	3	3	2	\$127	1.2	Car Lift	Power Liftgate may Fall Prematurely Causing injury - Software Update Required	38 (0.6%)
CHEVROLET	14291	3	3	3	\$32	0.3	No Car Lift	Low-beam Headlamps	36 (0.57%)
CHEVROLET	14535	3	3	3	\$32	0.3	No Car Lift	Carbon Monoxide Emissions	21 (0.33%)
CHEVROLET	N162064340	3	3	3			No Car Lift	Center High Mount Stop Lamp Water Leak	15 (0.24%)
CHEVROLET	01028	3	3	3	\$42	0.4	Programming Only	Generator Low Voltage Indicator Light PCM Reflash	12 (0.19%)
CHEVROLET	14648	3	3	3	\$42	0.4	No Car Lift	OnStar Gen 8.xC Module Inoperative/Vehicle Battery Discharged	11 (0.17%)
CHEVROLET	08157	3	3	3	\$21	0.2	No Car Lift	Instrument Panel Storage Bin Door Compliance - Add Reinforcement Bracket	9 (0.15%)
CHEVROLET	17200	3	3	3			No Car Lift	Loss of Electric Power Steering	7 (0.11%)
CHEVROLET	01035	3	3	3	\$21	0.2	No Car Lift	Fuel Return Line	6 (0.09%)
CHEVROLET	12312	3	3	3	\$42	0.4	Programming Only	Oil Life Monitor Update	5 (0.08%)
GMC	16007	5	5	3	\$32	0.3	No Car Lift	Frontal Airbag ad Pretensioner Non Deploy	345 (44.49%)
GMC	15822	5	5	4	\$74	0.7	No Car Lift	Seatbelt Lap Anchor Tensioner Cable (STOP SALE)	67 (8.65%)
GMC	20760	5	5	1	\$32	0.3	Car Lift	Brake Pedal Pivt Nut/Bolt Loose (STOP SALE)	22 (2.8%)
GMC	14030	5	5	5	\$191	1.8	Car Lift	Side Impact Airbag Connector (STOP SALE)	20 (2.53%)
GMC	14187	4	4	4	\$106	1.0	No Car Lift	Front Safety Belt Anchor (STOP SALE)	23 (2.94%)
GMC	04007	4	3	4	\$53	0.5	No Car Lift	Tailgate Support Cable	20 (2.59%)
GMC	10153	4	4	3	\$32	0.3	Programming Only	Heated Windshield Washer Module Short Circuit - Disable and Remove Module	13 (1.69%)
GMC	05068	4	4	2	\$106	1.0	Car Lift	Front Wheel Speed Sensor Corrosion *Salt States*	10 (1.29%)
GMC	14309	4	4	4	\$74	0.7	No Car Lift	Driver Door Switch Short Circuit	9 (1.16%)
GMC	02039	4	4	3	\$21	0.2	No Car Lift	Rearward Folding Head Restraints Pinch Point	7 (0.89%)
GMC	14581	4	3	4			No Car Lift	Carbon Monoxide Emissions	7 (0.86%)



Recall Summary Report

Date: 01/09/17

Radius: 25

Recall scoring key: 5 = High, 4 = Med, 3 = Low | Recalls excluded: 2 = Remedy not available, 1 = Non-safety related

Total Estimated VINs: 9,205

Make	OEM Code	Overall Score	Risk Score	Profit Score	Reimb. Labor	Labor Estimate	Service Difficulty	Recall Description	Recall Qty (%)
GMC	14271	4	4	4	\$95	0.9	No Car Lift	Power Seat Height Adjuster Bolt	6 (0.73%)
GMC	04087	4	4	3	\$32	0.3	No Car Lift	Tail Lamps/Stop Lamps	5 (0.7%)
GMC	05027	4	4	3	\$21	0.2	No Car Lift	Fuel Module Reservoir Assembly	5 (0.66%)
GMC	15240	3	3	2	\$127	1.2	Car Lift	Power Liftgate may Fall Prematurely Causing injury - Software Update Required	58 (7.52%)
GMC	SB13-04-S003A	3	3	2	\$74	0.7	Car Lift	Driver Door Short Circuit	56 (7.18%)
GMC	05037	3	3	3	\$21	0.2	No Car Lift	Second Row Center Safety Belt	14 (1.77%)
GMC	14291	3	3	3	\$32	0.3	No Car Lift	Low-beam Headlamps	13 (1.65%)