



Estimated Recalls By Distance Ford in Chicago Suburb

Date: 10/25/2023

Make	0-5 miles		6-10 miles		11-15 miles		16-20 miles		21-25 miles		26-35 miles		36-50 miles		51+ miles		Total	
	Market Size	Est. Recalls	Market Size	Est. Recalls	Market Size	Est. Recalls	Market Size	Est. Recalls	Market Size	Est. Recalls	Market Size	Est. Recalls	Market Size	Est. Recalls	Market Size	Est. Recalls	Market Size	Est. Recalls
FORD	2,403	601	16,594	4,152	21,872	5,472	25,417	6,356	24,883	6,226	66,428	16,620	120,284	30,094	-	-	277,881	69,521
Sub-Total	2,403	601	16,594	4,152	21,872	5,472	25,417	6,356	24,883	6,226	66,428	16,620	120,284	30,094	-	-	277,881	69,521
Running Total	2,403	601	18,997	4,753	40,869	10,225	66,286	16,581	91,169	22,807	157,597	39,427	277,881	69,521	277,881	69,521		

Zip Code	Make	City	Distance	Market Size	Running Total	Est. Recalls	Running Total
60084	FORD	LAKE BARRINGTON	0	1	1	0	0
60084	FORD	WAUCONDA	0	838	839	210	210
60042	FORD	ISLAND LAKE	3	453	1,292	113	323
60060	FORD	MUNDELEIN	5	1,111	2,403	278	601
60073	FORD	VOLO	6	2	2,405	1	602
60073	FORD	ROUND LAKE BEACH	6	5	2,410	1	603
60073	FORD	ROUND LAKE HEIGHTS	6	1	2,411	0	603
60073	FORD	HAINESVILLE	6	1	2,412	0	603
60073	FORD	ROUND LAKE	6	1,559	3,971	390	993
60013	FORD	OAKWOOD HILLS	6	2	3,973	1	994
60013	FORD	CARY	6	1,339	5,312	335	1,329
60021	FORD	FOX RIVER GROVE	6	274	5,586	69	1,398
60047	FORD	HAWTHORN WOODS	7	8	5,594	2	1,400
60047	FORD	KILDEER	7	3	5,597	1	1,401
60047	FORD	LAKE ZURICH	7	1,593	7,190	398	1,799
60030	FORD	HAINESVILLE	7	1	7,191	0	1,799
60030	FORD	GRAYS LAKE	7	1,441	8,632	360	2,159
60011	FORD	BARRINGTON	7	14	8,646	4	2,163
60041	FORD	INGLESIDE	7	414	9,060	104	2,267
60051	FORD	JOHNSBURG	7	10	9,070	3	2,270
60051	FORD	LAKEMOOR	7	4	9,074	1	2,271
60051	FORD	MCHENRY	7	1,351	10,425	338	2,609
60010	FORD	LAKE BARRINGTON	8	7	10,432	2	2,611
60010	FORD	BARRINGTON	8	2,233	12,665	558	3,169
60010	FORD	SOUTH BARRINGTON	8	3	12,668	1	3,170
60010	FORD	DEER PARK	8	5	12,673	1	3,171
60010	FORD	PORT BARRINGTON	8	2	12,675	1	3,172
60010	FORD	INVERNESS	8	1	12,676	0	3,172
60010	FORD	NORTH BARRINGTON	8	1	12,677	0	3,172
60010	FORD	TOWER LAKES	8	2	12,679	1	3,173
60020	FORD	FOX LAKE	9	433	13,112	108	3,281
60012	FORD	CRYSTAL LAKE	9	527	13,639	132	3,413
60050	FORD	MCHENRY	9	1,715	15,354	429	3,842
60050	FORD	MCCULLOM LAKE	9	1	15,355	0	3,842
60061	FORD	VERNON HILLS	10	618	15,973	155	3,997
60006	FORD	ARLINGTON HEIGHTS	10	5	15,978	1	3,998
60014	FORD	CRYSTAL LAKE	10	2,041	18,019	510	4,508
60014	FORD	VILLAGE OF LAKEWOOD	10	3	18,022	1	4,509
60048	FORD	LIBERTYVILLE	10	959	18,981	240	4,749
60039	FORD	CRYSTAL LAKE	10	16	18,997	4	4,753
60046	FORD	LINDENHURST	11	9	19,006	2	4,755
60046	FORD	LAKE VILLA	11	1,441	20,447	360	5,115
60074	FORD	PALATINE	11	1,071	21,518	268	5,383
60102	FORD	ALGONQUIN	11	1,610	23,128	403	5,786
60089	FORD	BUFFALO GROVE	12	1,167	24,295	292	6,078
60156	FORD	LAKE IN THE HILLS	12	1,363	25,658	341	6,419
60067	FORD	INVERNESS	12	2	25,660	1	6,420
60067	FORD	PALATINE	12	1,431	27,091	358	6,778
60069	FORD	LINCOLNSHIRE	12	228	27,319	57	6,835
60110	FORD	CARPENTERSVILLE	12	1,090	28,409	273	7,108
60031	FORD	GURNEE	13	1,224	29,633	306	7,414
60072	FORD	RINGWOOD	13	61	29,694	15	7,429
60081	FORD	SPRING GROVE	13	570	30,264	143	7,572
60192	FORD	HOFFMAN ESTATES	14	602	30,866	151	7,723
60004	FORD	ARLINGTON HEIGHTS	14	1,804	32,670	451	8,174
60065	FORD	NORTHBROOK	14	7	32,677	2	8,176
60118	FORD	WEST DUNDEE	14	6	32,683	2	8,178
60118	FORD	EAST DUNDEE	14	1	32,684	0	8,178
60118	FORD	SLEEPY HOLLOW	14	2	32,686	1	8,179
60118	FORD	DUNDEE	14	837	33,523	209	8,388
60044	FORD	LAKE BLUFF	14	255	33,778	64	8,452
60045	FORD	LAKE FOREST	14	631	34,409	158	8,610
60195	FORD	HOFFMAN ESTATES	14	1	34,410	0	8,610
60195	FORD	SCHAUMBURG	14	101	34,511	25	8,635
60078	FORD	PALATINE	14	5	34,516	1	8,636
60002	FORD	ANTIOCH	14	1,197	35,713	299	8,935
60097	FORD	WONDER LAKE	14	515	36,228	129	9,064
60008	FORD	ROLLING MEADOWS	15	709	36,937	177	9,241
60090	FORD	WHEELING	15	934	37,871	234	9,475
60064	FORD	NORTH CHICAGO	15	116	37,987	29	9,504
60088	FORD	GREAT LAKES	15	101	38,088	25	9,529
60169	FORD	HOFFMAN ESTATES	15	926	39,014	232	9,761
60015	FORD	RIVERWOODS	15	4	39,018	1	9,762
60015	FORD	BANNOCKBURN	15	1	39,019	0	9,762
60015	FORD	DEERFIELD	15	729	39,748	182	9,944
60085	FORD	WAUKEGAN	15	738	40,486	185	10,129
60085	FORD	PARK CITY	15	1	40,487	0	10,129
60083	FORD	OLD MILL CREEK	15	4	40,491	1	10,130
60083	FORD	BEACH PARK	15	2	40,493	1	10,131
60083	FORD	WADSWORTH	15	375	40,868	94	10,225
60168	FORD	SCHAUMBURG	15	1	40,869	0	10,225

Zip Code	Make	City	Distance	Market Size	Running Total	Est. Recalls	Running Total
60173	FORD	SCHAUMBURG	16	303	41,172	76	10,301
60079	FORD	WAUKEGAN	16	7	41,179	2	10,303
60070	FORD	PROSPECT HEIGHTS	16	427	41,606	107	10,410
60071	FORD	RICHMOND	16	223	41,829	56	10,466
60005	FORD	ARLINGTON HEIGHTS	16	933	42,762	233	10,699
60159	FORD	SCHAUMBURG	16	6	42,768	2	10,701
60194	FORD	SCHAUMBURG	16	681	43,449	170	10,871
53192	FORD	WILMOT	17	4	43,453	1	10,872
60136	FORD	GILBERTS	17	384	43,837	96	10,968
60098	FORD	BULL VALLEY	17	1	43,838	0	10,968
60098	FORD	WOODSTOCK	17	1,561	45,399	390	11,358
60142	FORD	HUNTLEY	17	2,137	47,536	534	11,892
60120	FORD	ELGIN	17	1,213	48,749	303	12,195
53179	FORD	TREVOR	17	527	49,276	132	12,327
60107	FORD	STREAMWOOD	17	1,267	50,543	317	12,644
60040	FORD	HIGHWOOD	17	91	50,634	23	12,667
60121	FORD	ELGIN	17	29	50,663	7	12,674
60087	FORD	WAUKEGAN	17	524	51,187	131	12,805
60087	FORD	BEACH PARK	17	2	51,189	1	12,806
60056	FORD	MOUNT PROSPECT	17	1,521	52,710	380	13,186
60193	FORD	SCHAUMBURG	18	1,402	54,112	351	13,537
60035	FORD	HIGHLAND PARK	18	684	54,796	171	13,708
53181	FORD	TWIN LAKES	18	636	55,432	159	13,867
60123	FORD	ELGIN	18	1,392	56,824	348	14,215
60062	FORD	NORTHBROOK	18	1,165	57,989	291	14,506
53109	FORD	CAMP LAKE	19	1	57,990	0	14,506
60075	FORD	RUSSELL	19	1	57,991	0	14,506
53101	FORD	BASSETT	19	1	57,992	0	14,506
60099	FORD	BEACH PARK	19	3	57,995	1	14,507
60099	FORD	ZION	19	699	58,694	175	14,682
60034	FORD	HEBRON	19	100	58,794	25	14,707
60009	FORD	ELK GROVE VILLAGE	19	2	58,796	1	14,708
60007	FORD	ELK GROVE VILLAGE	20	1,421	60,217	355	15,063
53170	FORD	SILVER LAKE	20	139	60,356	35	15,098
60026	FORD	GLENVIEW	20	375	60,731	94	15,192
60016	FORD	DES PLAINES	20	1,566	62,297	392	15,584
60180	FORD	UNION	20	125	62,422	31	15,615
60133	FORD	HANOVER PARK	20	988	63,410	247	15,862
60172	FORD	ROSELLE	20	1,088	64,498	272	16,134
60103	FORD	BARTLETT	20	1,788	66,286	447	16,581
53104	FORD	BRISTOL	21	577	66,863	144	16,725
60157	FORD	MEDINAH	21	136	66,999	34	16,759
60017	FORD	DES PLAINES	21	3	67,002	1	16,760
53128	FORD	GENOA CITY	21	644	67,646	161	16,921
60177	FORD	SOUTH ELGIN	21	972	68,618	243	17,164
60025	FORD	GLENVIEW	21	1,239	69,857	310	17,474
53159	FORD	POWERS LAKE	21	5	69,862	1	17,475
60022	FORD	GLENCOE	21	190	70,052	48	17,523
60143	FORD	ITASCA	21	433	70,485	108	17,631
60124	FORD	ELGIN	21	1,118	71,603	280	17,911
53142	FORD	KENOSHA	22	1,913	73,516	478	18,389
60096	FORD	WINTHROP HARBOR	22	320	73,836	80	18,469
53168	FORD	SALEM	22	712	74,548	178	18,647
53157	FORD	PELL LAKE	22	17	74,565	4	18,651
53158	FORD	PLEASANT PRAIRIE	22	1,196	75,761	299	18,950
60108	FORD	BLOOMINGDALE	22	965	76,726	241	19,191
60191	FORD	WOOD DALE	22	531	77,257	133	19,324
60018	FORD	DES PLAINES	22	816	78,073	204	19,528
60184	FORD	WAYNE	23	147	78,220	37	19,565
60093	FORD	WINNETKA	23	511	78,731	128	19,693
60093	FORD	NORTHFIELD	23	3	78,734	1	19,694
60140	FORD	PINGREE GROVE	23	6	78,740	2	19,696
60140	FORD	HAMPSHIRE	23	1,035	79,775	259	19,955
60068	FORD	PARK RIDGE	23	1,319	81,094	330	20,285
60029	FORD	GOLF	24	3	81,097	1	20,286
60106	FORD	BENSENVILLE	24	492	81,589	123	20,409
60714	FORD	NILES	24	836	82,425	209	20,618
60053	FORD	MORTON GROVE	24	605	83,030	151	20,769
60666	FORD	CHICAGO	24	2	83,032	1	20,770
60101	FORD	ADDISON	24	1,122	84,154	281	21,051
60139	FORD	GLENDALE HEIGHTS	24	915	85,069	229	21,280
60188	FORD	CAROL STREAM	24	1,776	86,845	444	21,724
53195	FORD	ZENDA	25	4	86,849	1	21,725
60174	FORD	SAINT CHARLES	25	1,362	88,211	341	22,066
60152	FORD	MARENGO	25	719	88,930	180	22,246
60091	FORD	WILMETTE	25	639	89,569	160	22,406
60043	FORD	KENILWORTH	25	74	89,643	19	22,425
60631	FORD	CHICAGO	25	1,140	90,783	285	22,710
60077	FORD	SKOKIE	25	386	91,169	97	22,807
60176	FORD	SCHILLER PARK	26	294	91,463	74	22,881
60175	FORD	SAINT CHARLES	26	1,237	92,700	309	23,190
60109	FORD	BURLINGTON	26	20	92,720	5	23,195
53143	FORD	KENOSHA	26	805	93,525	201	23,396
60656	FORD	CHICAGO	26	745	94,270	186	23,582
60185	FORD	NORTHWOODS	26	1	94,271	0	23,582
60185	FORD	WEST CHICAGO	26	1,217	95,488	304	23,886
60033	FORD	HARVARD	26	653	96,141	163	24,049
60131	FORD	FRANKLIN PARK	26	492	96,633	123	24,172
53147	FORD	LAKE GENEVA	26	1,490	98,123	373	24,545
60183	FORD	WASCO	26	6	98,129	2	24,547
60203	FORD	EVANSTON	26	91	98,220	23	24,570
60076	FORD	SKOKIE	27	534	98,754	134	24,704

Zip Code	Make	City	Distance	Market Size	Running Total	Est. Recalls	Running Total
60186	FORD	WEST CHICAGO	27	2	98,756	1	24,705
53144	FORD	KENOSHA	27	1,246	100,002	312	25,017
60706	FORD	NORRIDGE	27	4	100,006	1	25,018
60706	FORD	HARWOOD HEIGHTS	27	641	100,647	160	25,178
60201	FORD	EVANSTON	27	610	101,257	153	25,331
60138	FORD	GLEN ELLYN	27	11	101,268	3	25,334
60204	FORD	EVANSTON	27	7	101,275	2	25,336
60164	FORD	MELROSE PARK	27	629	101,904	157	25,493
60164	FORD	NORTHLAKE	27	5	101,909	1	25,494
53141	FORD	KENOSHA	27	5	101,914	1	25,495
60646	FORD	CHICAGO	27	798	102,712	200	25,695
60187	FORD	WHEATON	27	921	103,633	230	25,925
60190	FORD	WINFIELD	27	462	104,095	116	26,041
60126	FORD	ELMHURST	28	1,632	105,727	408	26,449
60712	FORD	LINCOLNWOOD	28	231	105,958	58	26,507
60148	FORD	LOMBARD	28	1,931	107,889	483	26,990
53171	FORD	SOMERS	28	6	107,895	2	26,992
60634	FORD	CHICAGO	28	1,590	109,485	398	27,390
60137	FORD	GLEN ELLYN	28	1,323	110,808	331	27,721
60181	FORD	VILLA PARK	28	1,079	111,887	270	27,991
53105	FORD	BURLINGTON	28	2,628	114,515	657	28,648
60171	FORD	RIVER GROVE	28	249	114,764	62	28,710
60630	FORD	CHICAGO	28	1,070	115,834	268	28,978
60202	FORD	EVANSTON	28	416	116,250	104	29,082
60165	FORD	STONE PARK	29	46	116,296	12	29,094
53148	FORD	LYONS	29	7	116,303	2	29,096
60163	FORD	BERKELEY	29	163	116,466	41	29,137
60134	FORD	GENEVA	29	1,253	117,719	313	29,450
53139	FORD	KANSASVILLE	29	327	118,046	82	29,532
53125	FORD	FONTANA	29	186	118,232	47	29,579
60161	FORD	MELROSE PARK	29	2	118,234	1	29,580
60160	FORD	MELROSE PARK	29	455	118,689	114	29,694
60645	FORD	CHICAGO	29	385	119,074	96	29,790
53140	FORD	KENOSHA	29	959	120,033	240	30,030
53176	FORD	SPRINGFIELD	29	1	120,034	0	30,030
60707	FORD	CHICAGO	29	260	120,294	65	30,095
60707	FORD	ELMWOOD PARK	29	653	120,947	163	30,258
60659	FORD	CHICAGO	29	230	121,177	58	30,316
60135	FORD	GENOA	30	316	121,493	79	30,395
60189	FORD	WHEATON	30	1,069	122,562	267	30,662
53191	FORD	WILLIAMS BAY	30	242	122,804	61	30,723
60104	FORD	BELLWOOD	30	455	123,259	114	30,837
53184	FORD	WALWORTH	30	349	123,608	87	30,924
60641	FORD	CHICAGO	30	904	124,512	226	31,150
60626	FORD	CHICAGO	30	353	124,865	88	31,238
53182	FORD	UNION GROVE	30	865	125,730	216	31,454
60162	FORD	HILLSIDE	30	242	125,972	61	31,515
60625	FORD	CHICAGO	30	588	126,560	147	31,662
60147	FORD	LAFOX	30	7	126,567	2	31,664
61038	FORD	GARDEN PRAIRIE	30	73	126,640	18	31,682
60510	FORD	BATAVIA	31	1,151	127,791	288	31,970
60305	FORD	RIVER FOREST	31	261	128,052	65	32,035
60555	FORD	WARRENVILLE	31	495	128,547	124	32,159
60153	FORD	MAYWOOD	31	432	128,979	108	32,267
60660	FORD	CHICAGO	31	314	129,293	79	32,346
60639	FORD	CHICAGO	31	721	130,014	180	32,526
60523	FORD	OAK BROOK	31	269	130,283	67	32,593
60302	FORD	OAK PARK	31	678	130,961	170	32,763
60301	FORD	OAK PARK	32	55	131,016	14	32,777
60618	FORD	CHICAGO	32	1,025	132,041	256	33,033
60154	FORD	WESTCHESTER	32	678	132,719	170	33,203
60303	FORD	OAK PARK	32	8	132,727	2	33,205
53177	FORD	MOUNT PLEASANT	32	1	132,728	0	33,205
53177	FORD	STURTEVANT	32	456	133,184	114	33,319
60155	FORD	MAYWOOD	32	2	133,186	1	33,320
60155	FORD	BROADVIEW	32	216	133,402	54	33,374
60640	FORD	CHICAGO	32	577	133,979	144	33,518
60522	FORD	OAK BROOK	32	5	133,984	1	33,519
60522	FORD	HINSDALE	32	1	133,985	0	33,519
60539	FORD	MOOSEHEART	32	2	133,987	1	33,520
60515	FORD	DOWNERS GROVE	32	993	134,980	248	33,768
60141	FORD	HINES	32	6	134,986	2	33,770
60130	FORD	FOREST PARK	32	353	135,339	88	33,858
60563	FORD	NAPERVILLE	32	1,200	136,539	300	34,158
60651	FORD	CHICAGO	33	711	137,250	178	34,336
60178	FORD	SYCAMORE	33	1,035	138,285	259	34,595
60151	FORD	MAPLE PARK	33	273	138,558	68	34,663
60304	FORD	OAK PARK	33	363	138,921	91	34,754
61012	FORD	CAPRON	33	114	139,035	29	34,783
60613	FORD	CHICAGO	33	618	139,653	155	34,938
60647	FORD	CHICAGO	33	679	140,332	170	35,108
60532	FORD	LISLE	33	923	141,255	231	35,339
53167	FORD	ROCHESTER	33	13	141,268	3	35,342
60119	FORD	ELBURN	33	523	141,791	131	35,473
60526	FORD	LA GRANGE PARK	33	482	142,273	121	35,594
53403	FORD	MOUNT PLEASANT	33	20	142,293	5	35,599
53403	FORD	RACINE	33	939	143,232	235	35,834
60644	FORD	CHICAGO	33	483	143,715	121	35,955
60502	FORD	AURORA	33	748	144,463	187	36,142
60567	FORD	NAPERVILLE	33	14	144,477	4	36,146
60542	FORD	NORTH AURORA	33	744	145,221	186	36,332
53401	FORD	RACINE	34	2	145,223	1	36,333

Zip Code	Make	City	Distance	Market Size	Running Total	Est. Recalls	Running Total
60657	FORD	CHICAGO	34	713	145,936	178	36,511
60559	FORD	WESTMONT	34	710	146,646	178	36,689
60514	FORD	CLARENDON HILLS	34	276	146,922	69	36,758
60546	FORD	NORTH RIVERSIDE	34	1	146,923	0	36,758
60546	FORD	RIVERSIDE	34	559	147,482	140	36,898
60521	FORD	HINSDALE	34	464	147,946	116	37,014
60513	FORD	BROOKFIELD	34	733	148,679	183	37,197
60558	FORD	WESTERN SPRINGS	34	432	149,111	108	37,305
60519	FORD	EOLA	34	1	149,112	0	37,305
60624	FORD	CHICAGO	34	319	149,431	80	37,385
60622	FORD	CHICAGO	34	416	149,847	104	37,489
60598	FORD	AURORA	34	6	149,853	2	37,491
53585	FORD	SHARON	35	185	150,038	46	37,537
60507	FORD	AURORA	35	10	150,048	3	37,540
60614	FORD	CHICAGO	35	677	150,725	169	37,709
60145	FORD	KINGSTON	35	121	150,846	30	37,739
60540	FORD	NAPERVILLE	35	1,500	152,346	375	38,114
53406	FORD	MOUNT PLEASANT	35	85	152,431	21	38,135
53406	FORD	RACINE	35	1,625	154,056	406	38,541
60402	FORD	BERWYN	35	1,555	155,611	389	38,930
60534	FORD	LYONS	35	299	155,910	75	39,005
60642	FORD	CHICAGO	35	190	156,100	48	39,053
60612	FORD	CHICAGO	35	292	156,392	73	39,126
60516	FORD	DOWNERS GROVE	35	1,205	157,597	301	39,427
53405	FORD	MOUNT PLEASANT	36	13	157,610	3	39,430
53405	FORD	RACINE	36	1,183	158,793	296	39,726
60804	FORD	CICERO	36	997	159,790	249	39,975
60505	FORD	AURORA	36	818	160,608	205	40,180
60144	FORD	KANEVILLE	36	6	160,614	2	40,182
53408	FORD	RACINE	36	7	160,621	2	40,184
61008	FORD	BELVIDERE	36	1,183	161,804	296	40,480
60610	FORD	CHICAGO	36	378	162,182	95	40,575
60566	FORD	NAPERVILLE	36	7	162,189	2	40,577
60525	FORD	HODGKINS	36	2	162,191	1	40,578
60525	FORD	COUNTRYSIDE	36	1	162,192	0	40,578
60525	FORD	INDIAN HEAD PARK	36	3	162,195	1	40,579
60525	FORD	LA GRANGE HIGHLANDS	36	2	162,197	1	40,580
60525	FORD	LA GRANGE	36	1,262	163,459	316	40,896
60623	FORD	CHICAGO	36	630	164,089	158	41,054
53121	FORD	ELKHORN	36	2,140	166,229	535	41,589
60504	FORD	AURORA	36	1,046	167,275	262	41,851
61065	FORD	POPLAR GROVE	36	517	167,792	129	41,980
53185	FORD	WATERFORD	36	1,837	169,629	459	42,439
60506	FORD	AURORA	37	1,246	170,875	312	42,751
60654	FORD	CHICAGO	37	192	171,067	48	42,799
60517	FORD	WOODRIDGE	37	1,133	172,200	283	43,082
53126	FORD	FRANKSVILLE	37	710	172,910	178	43,260
60661	FORD	CHICAGO	37	84	172,994	21	43,281
60112	FORD	CORTLAND	37	173	173,167	43	43,324
60561	FORD	DARIEN	37	1,058	174,225	265	43,589
60607	FORD	CHICAGO	37	246	174,471	62	43,651
60565	FORD	NAPERVILLE	37	1,563	176,034	391	44,042
60606	FORD	CHICAGO	37	36	176,070	9	44,051
60611	FORD	CHICAGO	37	387	176,457	97	44,148
60690	FORD	CHICAGO	37	12	176,469	3	44,151
60602	FORD	CHICAGO	37	5	176,474	1	44,152
60501	FORD	SUMMIT ARGO	37	195	176,669	49	44,201
53404	FORD	RACINE	38	469	177,138	117	44,318
60680	FORD	CHICAGO	38	15	177,153	4	44,322
60601	FORD	CHICAGO	38	139	177,292	35	44,357
60554	FORD	SUGAR GROVE	38	560	177,852	140	44,497
60604	FORD	CHICAGO	38	10	177,862	3	44,500
60603	FORD	CHICAGO	38	9	177,871	2	44,502
60527	FORD	BURR RIDGE	38	11	177,882	3	44,505
60527	FORD	WILLOWBROOK	38	924	178,806	231	44,736
60608	FORD	CHICAGO	38	553	179,359	138	44,874
53115	FORD	DELANAN	38	1,535	180,894	384	45,258
60632	FORD	CHICAGO	38	942	181,836	236	45,494
60605	FORD	CHICAGO	39	331	182,167	83	45,577
53114	FORD	DARIEN	39	255	182,422	64	45,641
60638	FORD	CHICAGO	39	1,741	184,163	435	46,076
60499	FORD	BEDFORD PARK	39	2	184,165	1	46,077
60564	FORD	NAPERVILLE	39	1,555	185,720	389	46,466
60503	FORD	AURORA	39	525	186,245	131	46,597
60458	FORD	JUSTICE	39	432	186,677	108	46,705
60538	FORD	MONTGOMERY	39	1,122	187,799	281	46,986
60440	FORD	BOLINGBROOK	39	1,621	189,420	405	47,391
60616	FORD	CHICAGO	39	524	189,944	131	47,522
53108	FORD	CALEDONIA	39	321	190,265	80	47,602
53120	FORD	EAST TROY	39	1,081	191,346	270	47,872
60480	FORD	WILLOW SPRINGS	40	312	191,658	78	47,950
60111	FORD	CLARE	40	29	191,687	7	47,957
60146	FORD	KIRKLAND	40	102	191,789	26	47,983
53402	FORD	RACINE	40	2,078	193,867	520	48,503
60455	FORD	BRIDGEVIEW	40	470	194,337	118	48,621
60609	FORD	CHICAGO	40	688	195,025	172	48,793
61011	FORD	CALEDONIA	40	153	195,178	38	48,831
60115	FORD	DEKALB	40	1,083	196,261	271	49,102
60629	FORD	CHICAGO	41	1,460	197,721	365	49,467
60457	FORD	HICKORY HILLS	41	529	198,250	132	49,599
60459	FORD	BURBANK	41	894	199,144	224	49,823
60490	FORD	BOLINGBROOK	41	722	199,866	181	50,004

Zip Code	Make	City	Distance	Market Size	Running Total	Est. Recalls	Running Total
60511	FORD	BIG ROCK	41	116	199,982	29	50,033
60653	FORD	CHICAGO	41	236	200,218	59	50,092
53525	FORD	CLINTON	41	461	200,679	115	50,207
61016	FORD	CHERRY VALLEY	42	235	200,914	59	50,266
60439	FORD	LEMONT	42	1,272	202,186	318	50,584
60636	FORD	CHICAGO	42	471	202,657	118	50,702
60512	FORD	BRISTOL	42	87	202,744	22	50,724
60652	FORD	CHICAGO	42	1,066	203,810	267	50,991
60454	FORD	OAK LAWN	42	3	203,813	1	50,992
60585	FORD	PLAINFIELD	42	1,038	204,851	260	51,252
60615	FORD	CHICAGO	42	287	205,138	72	51,324
60465	FORD	PALOS HILLS	42	691	205,829	173	51,497
53103	FORD	BIG BEND	43	442	206,271	111	51,608
53150	FORD	MUSKEGO	43	2,345	208,616	586	52,194
60621	FORD	CHICAGO	43	256	208,872	64	52,258
60456	FORD	HOMETOWN	43	196	209,068	49	52,307
60543	FORD	OSWEGO	43	1,921	210,989	480	52,787
60520	FORD	HINCKLEY	43	145	211,134	36	52,823
60453	FORD	OAK LAWN	43	2,406	213,540	602	53,425
53132	FORD	FRANKLIN	43	2,758	216,298	690	54,115
60415	FORD	CHICAGO RIDGE	43	406	216,704	102	54,217
53149	FORD	MUKWONAGO	43	2,132	218,836	533	54,750
60637	FORD	CHICAGO	44	257	219,093	64	54,814
61114	FORD	ROCKFORD	44	515	219,608	129	54,943
53505	FORD	AVALON	44	47	219,655	12	54,955
60805	FORD	EVERGREEN PARK	44	966	220,621	242	55,197
60482	FORD	WORTH	44	454	221,075	114	55,311
60446	FORD	ROMEDEVILLE	44	1,328	222,403	332	55,643
53154	FORD	OAK CREEK	44	2,585	224,988	646	56,289
61131	FORD	LOVES PARK	44	2	224,990	1	56,290
60464	FORD	PALOS PARK	44	504	225,494	126	56,416
61132	FORD	LOVES PARK	44	6	225,500	2	56,418
61107	FORD	ROCKFORD	44	788	226,288	197	56,615
60620	FORD	CHICAGO	44	1,250	227,538	313	56,928
61108	FORD	ROCKFORD	44	686	228,224	172	57,100
61111	FORD	LOVES PARK	44	685	228,909	171	57,271
61125	FORD	ROCKFORD	45	6	228,915	2	57,273
61073	FORD	ROSCOE	45	868	229,783	217	57,490
61126	FORD	ROCKFORD	45	8	229,791	2	57,492
60129	FORD	ESMOND	45	12	229,803	3	57,495
60150	FORD	MALTA	45	84	229,887	21	57,516
60544	FORD	PLAINFIELD	45	1,259	231,146	315	57,831
61052	FORD	MONROE CENTER	45	53	231,199	13	57,844
60619	FORD	CHICAGO	45	926	232,125	232	58,076
60655	FORD	CHICAGO	46	2,023	234,148	506	58,582
60545	FORD	PLANO	46	493	234,641	123	58,705
60649	FORD	CHICAGO	46	393	235,034	98	58,803
60463	FORD	PALOS HEIGHTS	46	788	235,822	197	59,000
61080	FORD	SOUTH BELOIT	46	403	236,225	101	59,101
61115	FORD	MACHESNEY PARK	46	732	236,957	183	59,284
53119	FORD	EAGLE	46	709	237,666	177	59,461
60803	FORD	CHICAGO	46	2	237,668	1	59,462
60803	FORD	ALSP	46	1,071	238,739	268	59,730
60643	FORD	CHICAGO	46	1,483	240,222	371	60,101
53172	FORD	SOUTH MILWAUKEE	47	1,358	241,580	340	60,441
53130	FORD	HALES CORNERS	47	517	242,097	129	60,570
53129	FORD	GREENDALE	47	810	242,907	203	60,773
60441	FORD	LOCKPORT	47	1,697	244,604	424	61,197
60441	FORD	HOMER GLEN	47	1	244,605	0	61,197
60491	FORD	HOMER GLEN	47	1,377	245,982	344	61,541
61109	FORD	ROCKFORD	47	604	246,586	151	61,692
61049	FORD	LINDENWOOD	47	37	246,623	9	61,701
60462	FORD	ORLAND PARK	47	1,939	248,562	485	62,186
60418	FORD	CRESTWOOD	47	372	248,934	93	62,279
60556	FORD	WATERMAN	48	113	249,047	28	62,307
60467	FORD	ORLAND PARK	48	1,348	250,395	337	62,644
53189	FORD	WAUKESHA	48	2,307	252,702	577	63,221
53190	FORD	WHITEWATER	48	1,070	253,772	268	63,489
60560	FORD	YORKVILLE	48	1,355	255,127	339	63,828
53153	FORD	NORTH PRAIRIE	48	266	255,393	67	63,895
60628	FORD	CHICAGO	48	1,376	256,769	344	64,239
60403	FORD	CREST HILL	48	684	257,453	171	64,410
61104	FORD	ROCKFORD	48	161	257,614	40	64,450
61110	FORD	ROCKFORD	48	4	257,618	1	64,451
60113	FORD	CRESTON	48	14	257,632	4	64,455
60586	FORD	PLAINFIELD	48	2,116	259,748	529	64,984
60445	FORD	MIDLOTHIAN	48	706	260,454	177	65,161
53221	FORD	MILWAUKEE	48	1,794	262,248	449	65,610
60406	FORD	BLUE ISLAND	48	520	262,768	130	65,740
60472	FORD	ROBBINS	48	105	262,873	26	65,766
53228	FORD	MILWAUKEE	49	918	263,791	230	65,996
53512	FORD	BELOIT	49	11	263,802	3	65,999
61103	FORD	ROCKFORD	49	472	264,274	118	66,117
61103	FORD	MACHESNEY PARK	49	17	264,291	4	66,121
53156	FORD	PALMYRA	49	322	264,613	81	66,202
53146	FORD	NEW BERLIN	49	650	265,263	163	66,365
60617	FORD	CHICAGO	49	1,594	266,857	399	66,764
53220	FORD	MILWAUKEE	49	1,441	268,298	360	67,124
53151	FORD	NEW BERLIN	49	2,451	270,749	613	67,737
53110	FORD	CUDAHY	49	1,265	272,014	316	68,053
61105	FORD	ROCKFORD	49	3	272,017	1	68,054
53546	FORD	JANESVILLE	49	2,263	274,280	566	68,620

Zip Code	Make	City	Distance	Market Size	Running Total	Est. Recalls	Running Total
60452	FORD	OAK FOREST	50	1,286	275,566	322	68,942
60548	FORD	SANDWICH	50	721	276,287	180	69,122
60435	FORD	JOLIET	50	1,448	277,735	362	69,484
53127	FORD	GENESEE DEPOT	50	3	277,738	1	69,485
60469	FORD	POSEN	50	143	277,881	36	69,521



Estimated Recall Summary Report

Ford Dealer in Chicago Suburb

Date: 10/25/2023

Prospect Radius: 50 mi
 Market Size: 277,881
 12 Mos. Forecast: 69,521

Recall scoring key: 5 = High, 4 = Med, 3 = Low | Recalls excluded: 2 = Remedy not available, 1 = Non-safety related

Please note: The numbers reflected in this report are raw estimates of open recalls in your requested area. Recall Masters reservation system is not applied to this report. After the enrollment process is completed, an updated count report with our reservation system applied is supplied before each campaign execution.

Make	OEM Code	NHTSA Code	Overall Score	Risk Score	Profit Score	Reimb. Labor	Labor Estimate	Service Difficulty	Recall Description	Recall Qty (%)
FORD	18532	18V735000	5	5	4	\$85	0.8	No Car Lift	Fuel Tank Deformation	3,247 (4.67%)
FORD	20530	20V331000	5	4	5	\$191	1.8	No Car Lift	Doors May Open While Driving	3,135 (4.51%)
FORD	19501	19V001000	5	5	4	\$74	0.7	No Car Lift	Takata Front Passenger Airbag Inflator	2,684 (3.86%)
FORD	22543	22V413000	5	5	5	\$339	3.2	No Car Lift	TRANSMISSION SHIFTER CABLE BUSHING	2,551 (3.67%)
FORD	16526	16V384000	5	5	5	\$307	2.9	No Car Lift	Takata Passenger Airbag Replacement	2,385 (3.43%)
FORD	21512	21V158000	5	5	4	\$95	0.9	No Car Lift	Driver's Airbag Inflator May Explode	2,259 (3.25%)
FORD	16530	16V643000	5	5	5	\$159	1.5	No Car Lift	Door Latch Replacement	1,933 (2.78%)
FORD	15521	15V319000	5	5	3	\$42	0.4	No Car Lift	Takata Driver Airbag Inflator	1,377 (1.98%)
FORD	18545	18V894000	5	5	2	\$106	1.0	Car Lift	Engine Block Heater Wire Assembly	1,307 (1.88%)
FORD	19517	19V435000	5	4	5	\$1,219	11.5	Car Lift	Rear Suspension Toe Links May Fracture	1,244 (1.79%)
FORD	09509	09V399000	5	5	4	\$64	0.6	No Car Lift	Speed Control System Modification	1,224 (1.76%)
FORD	05528	05V017000	5	5	1	\$32	0.3	Car Lift	Speed Control System Modification	1,203 (1.73%)
FORD	16541	16V777000	5	5	5	\$265	2.5	Car Lift	Fuel Delivery Module Flange Replacement	1,203 (1.73%)
FORD	18527	18V568000	5	5	4	\$95	0.9	No Car Lift	Carpet Shielding And Insulation Rework	1,196 (1.72%)
FORD	22573	22V859000	5	5	4	\$106	1.0	No Car Lift	Cracked Fuel Injector May Leak And Cause A Fire	1,043 (1.5%)
FORD	18508	18V167000	5	5	1	\$32	0.3	Car Lift	Steering Wheel	904 (1.3%)
FORD	11518	11V107000	5	5	4	\$53	0.5	No Car Lift	Driver Side Frontal Airbag Wire Harness Replacement	813 (1.17%)
FORD	19554	19V904000	5	4	5	\$201	1.9	No Car Lift	ABS Valve May Remain Open after ABS Event	695 (1%)
FORD	16542	16V875000	5	5	4	\$64	0.6	No Car Lift	Driver And Passenger Front Seatbelt Pretensioner Cable Separation	633 (0.91%)
FORD	18520	18V471000	5	5	2	\$64	0.6	Car Lift	Shift Lever	626 (0.9%)
FORD	17501	17V024000	5	5	4	\$64	0.6	No Car Lift	Passenger Airbag Inflator Replacement	542 (0.78%)
FORD	20562	20V675000	5	4	5	\$307	2.9	Car Lift	Rear Suspension Toe Link Fracture	528 (0.76%)
FORD	15534	15V793000	5	5	4	\$138	1.3	No Car Lift	Fuel Tank And Canister Purge Valve Inspection And Repair	466 (0.67%)
FORD	22506	22V082000	5	4	5	\$339	3.2	No Car Lift	Blank or Distorted Rearview Camera Image	466 (0.67%)
FORD	20515	20V177000	5	4	5	\$191	1.8	No Car Lift	Doors May Open While Driving	459 (0.66%)
FORD	14505	14V284000	5	4	5	\$201	1.9	Car Lift	Electric Power Steering	417 (0.6%)
FORD	23535	23V509000	5	4	5	\$191	1.8	Car Lift	Unexpected Activation Of Electric Parking Brake	410 (0.59%)
FORD	11521	11V385000	5	5	2	\$85	0.8	Car Lift	Fuel Tank Strap Inspection And Repair	396 (0.57%)
FORD	20R01		5	3	5	\$191	1.8	No Car Lift	Door Latch Replacement	389 (0.56%)
FORD	14R02		5	4	5	\$212	2.0	No Car Lift	Fuel Tank Corrosion Inspection and Repair	348 (0.5%)
FORD	17509	17V209000	5	5	4	\$64	0.6	No Car Lift	Coolant level sensor	348 (0.5%)
FORD	17542	17V787000	5	5	4	\$106	1.0	No Car Lift	Driver Side Airbag Inflator	334 (0.48%)
FORD	19529	19V651000	5	5	4	\$53	0.5	No Car Lift	Seat Frame Burred Edge	306 (0.44%)
FORD	19552	19V880000	5	5	4	\$74	0.7	No Car Lift	Fire After Seat Belt Pretensioner Deployment	306 (0.44%)
FORD	11516	11V030000	5	5	5	\$191	1.8	Car Lift	Subframe Front Lower Control Arm *Salt States*	285 (0.41%)
FORD	18501	18V046000	5	5	3	\$42	0.4	No Car Lift	Takata Front Passenger Airbag Inflator	285 (0.41%)
FORD	15518	15V340000	5	3	5	\$254	2.4	Car Lift	Possible Loss of Power Steering While Driving	278 (0.4%)
FORD	14502	14V165000	5	4	5	\$276	2.6	Car Lift	Front Subframe Crossbrace Installation	271 (0.39%)
FORD	19G01		5	5	4	\$127	1.2	No Car Lift	Engine Block Heater Cord Replacement	264 (0.38%)
FORD	14521	14V597000	5	4	5	\$180	1.7	Car Lift	Restraints Control Module Replacement	257 (0.37%)
FORD	15R02		5	5	5	\$212	2.0	Car Lift	Fuel Tank Corrosion Inspection And Repair	243 (0.35%)



Estimated Recall Summary Report

Ford Dealer in Chicago Suburb

Date: 10/25/2023

Prospect Radius: 50 mi
 Market Size: 277,881
 12 Mos. Forecast: 69,521

Recall scoring key: 5 = High, 4 = Med, 3 = Low | Recalls excluded: 2 = Remedy not available, 1 = Non-safety related

Please note: The numbers reflected in this report are raw estimates of open recalls in your requested area. Recall Masters reservation system is not applied to this report. After the enrollment process is completed, an updated count report with our reservation system applied is supplied before each campaign execution.

Make	OEM Code	NHTSA Code	Overall Score	Risk Score	Profit Score	Reimb. Labor	Labor Estimate	Service Difficulty	Recall Description	Recall Qty (%)
FORD	10S13	10V385000	5	5	5	\$191	1.8	Car Lift	Rear Axle Inspection And Repair	236 (0.34%)
FORD	14R01		5	5	3	\$21	0.2	No Car Lift	License Plate Lamp Assembly Replacement	229 (0.33%)
FORD	15S27	15V608000	5	5	2	\$117	1.1	Car Lift	Rear Axle Inspection	216 (0.31%)
FORD	15S02	15V040000	5	5	5	\$159	1.5	No Car Lift	Interior Door Handle Inspection And Repair	216 (0.31%)
FORD	14S08	14V285000	5	5	3	\$21	0.2	No Car Lift	License Lamp Assembly Replacement	195 (0.28%)
FORD	22S56	22V648000	5	5	5	\$329	3.1	No Car Lift	CLIMATE CONTROL BLOWER MOTOR REPLACEMENT	195 (0.28%)
FORD	05S27	05V030000	5	4	5	\$223	2.1	No Car Lift	Rear Door Latch Corrosion	174 (0.25%)
FORD	08C02	08V082000	5	5	3	\$21	0.2	No Car Lift	Passenger Airbag	174 (0.25%)
FORD	13S01	13V081000	5	5	5	\$329	3.1	No Car Lift	3rd Row Seat Latch Striker Corrosion Repair	167 (0.24%)
FORD	15S11	15V171000	5	4	5	\$159	1.5	No Car Lift	Interior Door Handle Inspection And Repair	167 (0.24%)
FORD	16B38		5	3	5	\$233	2.2	Programming Only	PCM Reprogramming And Canister Purge Valve Inspection	160 (0.23%)
FORD	22S21	22V191000	5	5	4	\$53	0.5	No Car Lift	Engine Oil Leak	160 (0.23%)
FORD	21C06	21V090000	5	5	4	\$138	1.3	No Car Lift	Inadequate Windshield Bonding	153 (0.22%)
FORD	22S27	22V255000	5	5	5	\$186	1.8	Car Lift	Explorer Rear Axle Bolt Fracture	153 (0.22%)
FORD	17S40	17V767000	5	5	1	\$32	0.3	Car Lift	Front Seat Adjuster Pivot Bolts	132 (0.19%)
FORD	16S03	16V036000	5	5	4	\$64	0.6	No Car Lift	Takata Driver Airbag Inflator Replacement	125 (0.18%)
FORD	16S19	16V248000	5	5	3	\$32	0.3	No Car Lift	Powertrain Control Module Reprogramming	125 (0.18%)
FORD	22S11	22V150000	5	4	5	\$159	1.5	Car Lift	Brake Master Cylinder May Leak Fluid into Booster	125 (0.18%)
FORD	22G01		5	2	5	\$848	8.0	Programming Only	Rear Climate Control Module Retrofit	125 (0.18%)
FORD	07S57	07V553000	5	5	3	\$21	0.2	No Car Lift	Camshaft Position (CMP) Sensor Inspection / Replacement	118 (0.17%)
FORD	04S17	04V332000	5	5	4	\$64	0.6	No Car Lift	Front Coil Spring Protective Shields *Salt States*	111 (0.16%)
FORD	16S24	16V345000	5	5	2	\$95	0.9	Car Lift	Brake Master Cylinder Replacement	111 (0.16%)
FORD	17S17	17V472000	5	5	4	\$53	0.5	No Car Lift	Seat Belt Mounting Bolts	111 (0.16%)
FORD	18S24	18V592000	5	5	3	\$32	0.3	No Car Lift	Charge Cord	111 (0.16%)
FORD	20B39		5	3	5	\$159	1.5	No Car Lift	Front View And Center High Mount Stop Lamp Camera Improper Function	111 (0.16%)
FORD	21S05	21V081000	5	5	3			No Car Lift	Frontal Airbag Inflator May Explode	111 (0.16%)
FORD	21S56	21V986000	5	3	5	\$212	2.0	Car Lift	LOOSE/SAGGING UNDERBODY INSULATORS	111 (0.16%)
FORD	13R01		5	4	5	\$159	1.5	Car Lift	Steering Column Shaft	97 (0.14%)
FORD	07S51	07V156000	5	4	5	\$159	1.5	No Car Lift	ABS Module Connector Inspection	97 (0.14%)
FORD	19S25	19V590000	5	5	4	\$64	0.6	No Car Lift	Seat Belt Anchor Pretensioner Cable	97 (0.14%)
FORD	15S22	15V322000	5	5	4	\$85	0.8	No Car Lift	Takata Passenger Airbag Inflator	90 (0.13%)
FORD	19S26	19V632000	5	4	5	\$509	4.8	Car Lift	Steering Gear Motor Bolt Corrosion	90 (0.13%)
FORD	11S25	12V006000	5	4	5	\$424	4.0	Car Lift	Torque Converter Replacement	83 (0.12%)
FORD	15S14	15V250000	5	5	5	\$456	4.3	Car Lift	Steering Gear Motor Bolt Corrosion	83 (0.12%)
FORD	15S31	15V712000	5	5	5	\$212	2.0	Car Lift	Fuel Tank Corrosion Inspection And Repair	83 (0.12%)
FORD	16C13	16V698000	5	5	3	\$32	0.3	No Car Lift	Body Control Module Reprogramming	76 (0.11%)
FORD	04S12	04V106000	5	5	4	\$64	0.6	No Car Lift	Stop Lamp Switch And Wire Harness Replacement	70 (0.1%)
FORD	17C12	17V526000	5	5	3	\$42	0.4	No Car Lift	Left Hand Rear Seatbelt Buckle Inspection	70 (0.1%)
FORD	22C12	22V451000	5	5	5	\$212	2.0	No Car Lift	WINDSHIELD ADHESION REPAIR	70 (0.1%)
FORD	22C22	22V686000	5	3	5	\$233	2.2	No Car Lift	The Park Position Lamp On Your Vehicle May Flicker	70 (0.1%)
FORD	14S06	14V286000	5	4	5	\$244	2.3	Car Lift	Electric Power Steering	63 (0.09%)



Estimated Recall Summary Report

Ford Dealer in Chicago Suburb

Date: 10/25/2023

Prospect Radius: 50 mi
 Market Size: 277,881
 12 Mos. Forecast: 69,521

Recall scoring key: 5 = High, 4 = Med, 3 = Low | Recalls excluded: 2 = Remedy not available, 1 = Non-safety related

Please note: The numbers reflected in this report are raw estimates of open recalls in your requested area. Recall Masters reservation system is not applied to this report. After the enrollment process is completed, an updated count report with our reservation system applied is supplied before each campaign execution.

Make	OEM Code	NHTSA Code	Overall Score	Risk Score	Profit Score	Reimb. Labor	Labor Estimate	Service Difficulty	Recall Description	Recall Qty (%)
FORD	01S21	01V227001	5	4	5	\$223	2.1	No Car Lift	Seat Belt Buckle	49 (0.07%)
FORD	17S34	17V668000	5	5	3	\$42	0.4	No Car Lift	Trailer Module Fuse And Footwell Drainage Hole	49 (0.07%)
FORD	22S47	22V484000	5	5	5	\$180	1.7	No Car Lift	UNDER HOOD FIRE	49 (0.07%)
FORD	22S20	22V192000	5	3	5	\$318	3.0	No Car Lift	WINDSHIELD RESEAL	42 (0.06%)
FORD	22S53	22V623000	5	4	5	\$223	2.1	Car Lift	Damaged Driveshaft May Fracture	42 (0.06%)
FORD	13S08	13V385000	5	4	5	\$159	1.5	Car Lift	Steering Column Shaft	35 (0.05%)
FORD	03C05	03V459000	5	5	3	\$21	0.2	No Car Lift	Lower Seat-To-Floor Latches	35 (0.05%)
FORD	16S18	16V245000	5	5	2	\$64	0.6	Car Lift	Rear Suspension Toe Link Replacement	35 (0.05%)
FORD	18S02	18V023000	5	5	4	\$74	0.7	No Car Lift	Takata Driver Side Airbag Inflator	35 (0.05%)
FORD	14S17	14V495000	5	5	2	\$127	1.2	Car Lift	Engine Wiring Splice Repair	28 (0.04%)
FORD	02S42	02V289000	5	4	5	\$180	1.7	Car Lift	Pinch Bolt Torque And Zetec Engine Battery Cable Routing	28 (0.04%)
FORD	17B16		5	3	5	\$318	3.0	No Car Lift	Battery Junction Box Clean and Seal	28 (0.04%)
FORD	19S40	19V805000	5	5	3	\$32	0.3	No Car Lift	Excessive Sealant Adhesive On Battery Cable	28 (0.04%)
FORD	19S43	19V839000	5	4	5	\$286	2.7	No Car Lift	Intermittent Or Inoperative Tail Lights	28 (0.04%)
FORD	21E14		5	2	5	\$318	3.0	Programming Only	Powertrain Control Module Reprogramming	28 (0.04%)
FORD	22S22	22V256000	5	4	5	\$1,081	10.2	Car Lift	Unintentional Rollaway Due to Transmission Washer	28 (0.04%)
FORD	22S36	22V346000	5	5	5	\$254	2.4	No Car Lift	Engine Compartment Fire	28 (0.04%)
FORD	13S04	13V227000	5	4	5	\$307	2.9	Car Lift	Fuel Delivery Module Replacement	21 (0.03%)
FORD	02S33	02V072000	5	4	5	\$159	1.5	No Car Lift	Electrical Connector/Sealer Skip	21 (0.03%)
FORD	20B34		5	3	5	\$170	1.6	No Car Lift	Transmission Oil Cooler	21 (0.03%)
FORD	21C25	21V811000	5	4	5	\$170	1.6	No Car Lift	Front Passenger Outboard Seatbelt Retractor Webbing Incorrectly Routed	21 (0.03%)
FORD	22S37	Awaiting#	5	5	4	\$106	1.0	Programming Only	Powertrain Control Module Reprogramming	21 (0.03%)
FORD	22B39		5	3	5	\$392	3.7	No Car Lift	Maverick No Start Condition	21 (0.03%)
FORD	14C03	14V164000	5	4	5	\$244	2.3	Car Lift	Front Seat Back frame Replacement	14 (0.02%)
FORD	07S48	07V079000	5	3	5	\$170	1.6	No Car Lift	16 Steel Wheel Replacement	14 (0.02%)
FORD	14S10	14V393000	5	5	5	\$191	1.8	No Car Lift	Right-Hand Front Halfshaft Retention Inspection / Repair	14 (0.02%)
FORD	14C11	14V736000	5	5	3	\$32	0.3	Programming Only	Key Removal When Not In Park	14 (0.02%)
FORD	16S06	16V111000	5	5	3	\$21	0.2	No Car Lift	Seat belt Bucker Repair / Replacement	14 (0.02%)
FORD	16S31	16V621000	5	5	4	\$74	0.7	No Car Lift	Fuel Pump Control Module Inspection and Repair	14 (0.02%)
FORD	18S07	18V169000	5	5	3	\$32	0.3	No Car Lift	Transmission Clutch	14 (0.02%)
FORD	20E04		5	3	5	\$371	3.5	No Car Lift	Exhaust Gas Recirculation (EGR) By-Pass Valve Replacement	14 (0.02%)
FORD	19S22	19V515000	5	5	5	\$223	2.1	Car Lift	Stuck Canister Purge Valve May Cause Stall	14 (0.02%)
FORD	21S42	21V712000	5	4	5	\$329	3.1	No Car Lift	Inadequate Panoramic Roof Glass Panel Bonding	14 (0.02%)
FORD	22S65	22V791000	5	5	4	\$64	0.6	Programming Only	TRANSIT AND E-TRANSIT HVAC INOPERABLE	14 (0.02%)
FORD	23S08	23V125000	5	5	4	\$53	0.5	No Car Lift	Passenger Airbag Inflator Inspection	14 (0.02%)
FORD	21C25	21V811000	5	4	5	\$170	1.6	No Car Lift	Seat Belt Routed Incorrectly	14 (0.02%)
FORD	13S12	13V584000	5	5	2	\$74	0.7	Car Lift	Overheating Of Engine Cylinder Head	7 (0.01%)
FORD	14S25	14V704000	5	5	2	\$148	1.4	Car Lift	Upper Intermediate Steering Shaft Inspection And Repair	7 (0.01%)
FORD	03C03	03V087000	5	4	5	\$170	1.6	Car Lift	Windshield Replacement	7 (0.01%)
FORD	10C11	10V161000	5	5	5	\$329	3.1	No Car Lift	Front Seat Manual Recliner Replacement	7 (0.01%)
FORD	02S40	02V266000	5	5	1	\$32	0.3	Car Lift	Pedal Lateral Spacing	7 (0.01%)



Estimated Recall Summary Report

Ford Dealer in Chicago Suburb

Date: 10/25/2023

Prospect Radius: 50 mi
 Market Size: 277,881
 12 Mos. Forecast: 69,521

Recall scoring key: 5 = High, 4 = Med, 3 = Low | Recalls excluded: 2 = Remedy not available, 1 = Non-safety related

Please note: The numbers reflected in this report are raw estimates of open recalls in your requested area. Recall Masters reservation system is not applied to this report. After the enrollment process is completed, an updated count report with our reservation system applied is supplied before each campaign execution.

Make	OEM Code	NHTSA Code	Overall Score	Risk Score	Profit Score	Reimb. Labor	Labor Estimate	Service Difficulty	Recall Description	Recall Qty (%)
FORD	10C13	10V316000	5	5	3	\$21	0.2	No Car Lift	Headliner Pushpin Replacement	7 (0.01%)
FORD	99S32	99V311000	5	5	5	\$170	1.6	Car Lift	Rollover Fuel System Impact	7 (0.01%)
FORD	11C20	11V445000	5	5	5	\$180	1.7	Car Lift	Possible Defective Windshield - Inspect And Replace	7 (0.01%)
FORD	14S26	14V777000	5	3	5	\$286	2.7	Car Lift	Remove And Install Sliding Door Plastic Panels	7 (0.01%)
FORD	15S13	15V005000	5	4	5	\$254	2.4	Car Lift	Fuel Pump Replacement	7 (0.01%)
FORD	00S22	00V231000	5	3	5	\$159	1.5	No Car Lift	Fuel Line	7 (0.01%)
FORD	15C09	15V339000	5	5	5	\$297	2.8	No Car Lift	Passenger Fixed Seat Restraint Anchorage Point	7 (0.01%)
FORD	15S29	15V614000	5	5	4	\$74	0.7	Programming Only	Adaptive Cruise Control	7 (0.01%)
FORD	16S13		5	5	5	\$657	6.2	No Car Lift	Side Curtain Airbag Inspection And Adjustment	7 (0.01%)
FORD	15S19	15V339000	5	5	5	\$297	2.8	No Car Lift	Underbody Temperatures	7 (0.01%)
FORD	15S03	15V050000	5	5	4	\$64	0.6	No Car Lift	Safety Belt And Cargo Hook Fastener Replacement	7 (0.01%)
FORD	17C02	17V123000	5	5	3	\$32	0.3	No Car Lift	Takata Driver Airbag Module Replacement	7 (0.01%)
FORD	17B25		5	3	5	\$223	2.1	No Car Lift	Exhaust Odor And Carbon Monoxide Complaints	7 (0.01%)
FORD	18S37	18V805000	5	5	3	\$21	0.2	No Car Lift	Seat Occupant	7 (0.01%)
FORD	19S41	19V809000	5	5	4	\$64	0.6	No Car Lift	Battery Cable May Chafe And Cause Electrical Short	7 (0.01%)
FORD	20S08	20V098000	5	5	5	\$233	2.2	Car Lift	Engine Block Heater Cord Inspection	7 (0.01%)
FORD	20S22	20V260000	5	4	5	\$318	3.0	No Car Lift	Panoramic Roof Panel May Separate From Vehicle	7 (0.01%)
FORD	20S73	20V795000	5	5	5	\$159	1.5	Car Lift	Engine Cover May Be Excessively Hot	7 (0.01%)
FORD	21S17	21V202000	5	4	5	\$223	2.1	Car Lift	Inadequate Rear Axle Oil Fill Volume	7 (0.01%)
FORD	21S38	21V625000	5	5	5	\$413	3.9	Car Lift	Fuel Delivery Module (FDM) Line Leak	7 (0.01%)
FORD	21C20	21V653000	5	4	5	\$180	1.7	No Car Lift	Front Seatbelt Webbing Routed Incorrectly	7 (0.01%)
FORD	22S01	22V013000	5	4	5	\$212	2.0	Car Lift	Secondary Fuel Filter Leak	7 (0.01%)
FORD	22S48	22V346000	5	5	4	\$117	1.1	No Car Lift	Engine Compartment Fire	7 (0.01%)
FORD	22C11	22V415000	5	4	5	\$212	2.0	Programming Only	INSTRUMENT PANEL CLUSTER SOFTWARE UPDATE	7 (0.01%)
FORD	21S31	21V536000	5	5	5	\$159	1.5	Car Lift	Spring Seat Interface Weld	7 (0.01%)
FORD	16R01		5	4	5	\$212	2.0	No Car Lift	Side Door Latch	7 (0.01%)
FORD	21S31	21V536000	5	5	5	\$159	1.5	Car Lift	Driveshaft May Separate	7 (0.01%)
FORD	22S15	22V188000	5	5	4	\$53	0.5	Programming Only	Transmission May Shift into Neutral While Driving	7 (0.01%)
FORD	19S07	19V075000	4	4	3	\$32	0.3	Programming Only	Unexpected Transmission Downshift	1,203 (1.73%)
FORD	21S22	21V316000	4	4	4	\$95	0.9	No Car Lift	Roof Rail Covers May Detach	765 (1.1%)
FORD	20C19	20V575000	4	4	4	\$85	0.8	No Car Lift	Distorted Or Inoperative Rearview Camera	758 (1.09%)
FORD	20S42	20V469000	4	4	2	\$106	1.0	Car Lift	Front Brake Hoses Could Rupture	570 (0.82%)
FORD	23S02	23V022000	4	4	4	\$64	0.6	Programming Only	Rearview Camera Image May Not Display	501 (0.72%)
FORD	21E01		4	3	4	\$74	0.7	Programming Only	Calibration For Nitrogen Oxide (NOx) Sensor Faults	459 (0.66%)
FORD	12S37	12V353000	4	4	3	\$32	0.3	No Car Lift	Engine Cover Modification	382 (0.55%)
FORD	19S38	19V767000	4	4	2	\$117	1.1	Car Lift	Driveshaft Coupling May Fail	320 (0.46%)
FORD	23S23	23V342000	4	3	4	\$74	0.7	Programming Only	Inoperative Rear 360 Degree Camera with a Blue Screen	313 (0.45%)
FORD	15R01		4	3	4	\$106	1.0	No Car Lift	EPS Motor Bolts	285 (0.41%)
FORD	22M03		4	3	4	\$138	1.3	No Car Lift	Replace Front And Or Side Cameras If Foggy	264 (0.38%)
FORD	19C07	19V633000	4	4	4	\$127	1.2	No Car Lift	Mechanical Seat Recliner	257 (0.37%)
FORD	20S31	20V332000	4	4	2	\$148	1.4	Car Lift	Brake Master Cylinder May Leak Into Booster	257 (0.37%)



Estimated Recall Summary Report

Ford Dealer in Chicago Suburb

Date: 10/25/2023

Prospect Radius: 50 mi
 Market Size: 277,881
 12 Mos. Forecast: 69,521

Recall scoring key: 5 = High, 4 = Med, 3 = Low | Recalls excluded: 2 = Remedy not available, 1 = Non-safety related

Please note: The numbers reflected in this report are raw estimates of open recalls in your requested area. Recall Masters reservation system is not applied to this report. After the enrollment process is completed, an updated count report with our reservation system applied is supplied before each campaign execution.

Make	OEM Code	NHTSA Code	Overall Score	Risk Score	Profit Score	Reimb. Labor	Labor Estimate	Service Difficulty	Recall Description	Recall Qty (%)
FORD	20S04	20V072000	4	4	2	\$127	1.2	Car Lift	Rear Suspension Toe Links May Fracture	236 (0.34%)
FORD	22S12	22V142000	4	4	4	\$74	0.7	No Car Lift	Windshield Wiper Motor May Fail	222 (0.32%)
FORD	15S39	15V861000	4	4	3	\$21	0.2	No Car Lift	Inoperative Headlights	167 (0.24%)
FORD	19S48	19V864000	4	4	4	\$138	1.3	No Car Lift	Tailgate May Open Unexpectedly	160 (0.23%)
FORD	22S17	22V193000	4	4	3	\$42	0.4	Programming Only	REPROGRAM INTEGRATED TRAILER RELAY MODULE	160 (0.23%)
FORD	14S22	14V682000	4	4	1	\$32	0.3	Car Lift	Fuel Tank Corrosion Inspection And Repair	153 (0.22%)
FORD	11S24	12V005000	4	4	4	\$53	0.5	No Car Lift	ABS Relay Installation And Master Cylinder Reservoir Cap Replacement	146 (0.21%)
FORD	04S20	04V442000	4	4	4	\$138	1.3	No Car Lift	Liftgate Glass Hinge And Ball Stud Bracket (If Applicable) Replacement	146 (0.21%)
FORD	14E03		4	3	4	\$74	0.7	Programming Only	Reprogram Powertrain Control Module	146 (0.21%)
FORD	21S43	21V746000	4	4	2	\$85	0.8	Car Lift	Rear Suspension Toe Link Fracture	146 (0.21%)
FORD	17S15	17V408000	4	4	2	\$74	0.7	Car Lift	Driveshaft Coupling	139 (0.2%)
FORD	20C03	20V097000	4	4	3	\$32	0.3	Programming Only	Daytime Running Lights May Not Dim	139 (0.2%)
FORD	14S07	14E028000	4	4	3	\$21	0.2	No Car Lift	All Weather Floor Mat Replacement	125 (0.18%)
FORD	08S05	08V208000	4	4	4	\$74	0.7	No Car Lift	Brake Booster Vacuum Hose Replacement	125 (0.18%)
FORD	03S04	03V281000	4	4	3	\$21	0.2	No Car Lift	Driver Seat Recliner Bolt	125 (0.18%)
FORD	21S24	21V376000	4	4	4	\$53	0.5	No Car Lift	Unintentional Rollaway Due To Detached Shift Cable	118 (0.17%)
FORD	11S15	11V049000	4	4	3	\$21	0.2	No Car Lift	Door Handle Reinforcement	104 (0.15%)
FORD	22S35	22V337000	4	4	3			No Car Lift	Driver's Air Bag May Not Deploy - CLOCKSPRING CONTAMINATION	90 (0.13%)
FORD	15C06	15V436000	4	4	3	\$21	0.2	Programming Only	Body Control Module Reprogramming	76 (0.11%)
FORD	22C20	22V594000	4	4	4	\$117	1.1	No Car Lift	Side Curtain Air Bag Malfunction	76 (0.11%)
FORD	21S53	21V983000	4	4	3	\$42	0.4	No Car Lift	Tailgate May Open Unexpectedly	70 (0.1%)
FORD	20E07		4	2	4	\$53	0.5	Programming Only	Powertrain Control Module Reprogramming	70 (0.1%)
FORD	23E09		4	3	4	\$53	0.5	Programming Only	Reprogram Powertrain Control Module	70 (0.1%)
FORD	06C12	06V111000	4	4	4	\$127	1.2	No Car Lift	Perform Prior To Vehicle Delivery - FMVSS 201U Compliance	63 (0.09%)
FORD	19C10	19V808000	4	4	3	\$32	0.3	Programming Only	Daytime Running Lights (DRL) May Not Dim	56 (0.08%)
FORD	14S04	14V237000	4	4	3	\$21	0.2	Programming Only	Reprogram Restraints Control Module	49 (0.07%)
FORD	14S03	14V239000	4	4	4	\$64	0.6	No Car Lift	Exterior Door Handle Inspection And Adjustment	49 (0.07%)
FORD	01S24	01V258000	4	4	2	\$95	0.9	Car Lift	Wiper Motor Gear Cover	49 (0.07%)
FORD	03S03	03V280000	4	4	1	\$42	0.4	Car Lift	Speed Control Cable Inspection/Replacement	49 (0.07%)
FORD	22S09	22V087000	4	4	2	\$74	0.7	Car Lift	LOOSE/SAGGING UNDERBODY INSULATOR	49 (0.07%)
FORD	22S44	22A11000	4	3	4	\$64	0.6	No Car Lift	REAR DOOR CHILD SAFETY LOCK INSPECTION	49 (0.07%)
FORD	14S19	14V526000	4	4	2	\$117	1.1	Car Lift	Motor Electronics Coolant Pump Replacement	42 (0.06%)
FORD	11S23	11V574000	4	4	2	\$85	0.8	Car Lift	Wheel Stud and Rear Brake Disc Inspection and Lug Nut Replacement	42 (0.06%)
FORD	18S10	18V214000	4	4	3	\$32	0.3	No Car Lift	Transmission Park	42 (0.06%)
FORD	19E02		4	3	4	\$53	0.5	No Car Lift	Powertrain Control Module Reprogramming	42 (0.06%)
FORD	22C27	22V825000	4	4	3	\$21	0.2	Programming Only	Rearview Camera Malfunction	42 (0.06%)
FORD	04C09	04V602000	4	4	2	\$53	0.5	Car Lift	Liftgate Latch Release Rod And Handle Assembly Return Spring Replacement	35 (0.05%)
FORD	04S23	04V445000	4	4	3	\$21	0.2	No Car Lift	Air Filter Element Replacement - Excluding Diesel	35 (0.05%)
FORD	15C03	15V406000	4	4	3	\$32	0.3	Programming Only	Reprogram Instrument Panel Cluster	35 (0.05%)
FORD	21C24	21V765000	4	4	3	\$42	0.4	No Car Lift	REAR SEAT CHILD RESTRAINT ANCHORAGE SYSTEM	35 (0.05%)
FORD	23B11		4	3	4	\$53	0.5	No Car Lift	Install New Dash Mat	35 (0.05%)



Estimated Recall Summary Report

Ford Dealer in Chicago Suburb

Date: 10/25/2023

Prospect Radius: 50 mi
 Market Size: 277,881
 12 Mos. Forecast: 69,521

Recall scoring key: 5 = High, 4 = Med, 3 = Low | Recalls excluded: 2 = Remedy not available, 1 = Non-safety related

Please note: The numbers reflected in this report are raw estimates of open recalls in your requested area. Recall Masters reservation system is not applied to this report. After the enrollment process is completed, an updated count report with our reservation system applied is supplied before each campaign execution.

Make	OEM Code	NHTSA Code	Overall Score	Risk Score	Profit Score	Reimb. Labor	Labor Estimate	Service Difficulty	Recall Description	Recall Qty (%)
FORD	12C26	12V488000	4	4	3	\$21	0.2	No Car Lift	Reprogram Restraint Control Module	28 (0.04%)
FORD	14E04		4	4	3	\$42	0.4	Programming Only	Reprogram Powertrain Control Module	28 (0.04%)
FORD	04S22	04V444000	4	4	3	\$21	0.2	No Car Lift	Anti-Lock Brake System (ABS) Module Service	28 (0.04%)
FORD	04S11	04V105000	4	4	3	\$21	0.2	No Car Lift	Air Filter Element Replacement	28 (0.04%)
FORD	23B57		4	2	4	\$64	0.6	No Car Lift	High Voltage Battery Module Replacement and/or BECM Software Update	28 (0.04%)
FORD	04S25	04V574000	4	4	1	\$42	0.4	Car Lift	Accelerator Cable Replacement	21 (0.03%)
FORD	00S37	00V349000	4	4	2	\$74	0.7	Car Lift	Park Brake Control Assembly	21 (0.03%)
FORD	05S40	05V520000	4	4	4	\$64	0.6	No Car Lift	Wiper Motor Inspection	21 (0.03%)
FORD	08S03	08V058000	4	4	4	\$53	0.5	No Car Lift	Interior Door Handles	21 (0.03%)
FORD	06C11	06V033000	4	4	1	\$32	0.3	Car Lift	Instrument Cluster Communication-Recalibration	21 (0.03%)
FORD	14E08		4	3	4	\$64	0.6	Programming Only	Reprogram Powertrain Control Module	21 (0.03%)
FORD	16B15		4	4	3	\$42	0.4	No Car Lift	Driver Airbag Inflator Replacement	21 (0.03%)
FORD	20S52	20V573000	4	4	3	\$42	0.4	No Car Lift	Brake Pedal Bracket Fracture	21 (0.03%)
FORD	21C18	21V592000	4	4	4	\$85	0.8	No Car Lift	Seat Belt Locking Retractor Malfunction	21 (0.03%)
FORD	22S37	22V382000	4	4	3	\$32	0.3	Programming Only	Powertrain Control Module Malfunction	21 (0.03%)
FORD	02S41	02V288000	4	4	2	\$53	0.5	Car Lift	Pinch Bolt Torque And Zetec Engine Battery Cable Routing	14 (0.02%)
FORD	03E05		4	4	2	\$74	0.7	Car Lift	Evaporative Emission Fresh Air Vent Hose	14 (0.02%)
FORD	03S10	03V507000	4	4	3	\$21	0.2	No Car Lift	SeatBelt Buckle Cover	14 (0.02%)
FORD	05S32	05V206000	4	4	3	\$21	0.2	No Car Lift	Dash Outer Insulator	14 (0.02%)
FORD	04S13	04V165000	4	4	3	\$42	0.4	No Car Lift	Powertrain Control Module Re-Calibration	14 (0.02%)
FORD	06S43	06V108000	4	4	3	\$32	0.3	No Car Lift	Carpet Interference With Accelerator Pedal	14 (0.02%)
FORD	06E17		4	3	4	\$74	0.7	Programming Only	Control Module Calibration	14 (0.02%)
FORD	08S01	08V051000	4	4	3	\$42	0.4	No Car Lift	Service Wiring Harness Replacement	14 (0.02%)
FORD	14E02		4	4	4	\$53	0.5	Programming Only	Reprogram Powertrain Control Module	14 (0.02%)
FORD	00B40		4	4	4	\$53	0.5	No Car Lift	Multifunction Switch	14 (0.02%)
FORD	15E03		4	3	4	\$53	0.5	No Car Lift	Powertrain Control Module Reprogramming	14 (0.02%)
FORD	98S14		4	4	2	\$85	0.8	Car Lift	Wheel Attachments - Lug Nuts	14 (0.02%)
FORD	20S63	20V692000	4	4	2	\$64	0.6	Car Lift	Link Shaft Brackets May Fracture	14 (0.02%)
FORD	21S10	21V155000	4	4	2	\$117	1.1	Car Lift	Tire Failure May Cause Sudden Air Loss	14 (0.02%)
FORD	22S15		4	3	4	\$53	0.5	Programming Only	Powertrain Control Module Software Update	14 (0.02%)
FORD	22S14	22V151000	4	3	4	\$106	1.0	Programming Only	Blank or Distorted Rearview Camera Image	14 (0.02%)
FORD	22S41	22V412000	4	3	4	\$64	0.6	Programming Only	BATTERY ENERGY CONTROL MODULE SOFTWARE UPDATE	14 (0.02%)
FORD	23B51		4	3	4	\$53	0.5	No Car Lift	Power Steering Cooler Bracket Replacement	14 (0.02%)
FORD	00E10		4	4	2	\$117	1.1	Car Lift	Fuel Delivery Module	7 (0.01%)
FORD	05E15		4	4	2	\$148	1.4	Car Lift	Exhaust Pressure Sensor Replacement	7 (0.01%)
FORD	00S21	00V228001	4	4	4	\$148	1.4	No Car Lift	Seat Belt Buckle Assembly	7 (0.01%)
FORD	12E06		4	4	3	\$21	0.2	Programming Only	Reprogram Powertrain Control Module	7 (0.01%)
FORD	05S33	05V266000	4	4	3	\$21	0.2	No Car Lift	Fuel Line Retainer Clip Installation	7 (0.01%)
FORD	05E16		4	3	4	\$74	0.7	Programming Only	Engine Control Modules Recalibration	7 (0.01%)
FORD	13E04		4	4	3	\$32	0.3	No Car Lift	PCM Configuration Error	7 (0.01%)
FORD	08C04	08V191000	4	4	4	\$95	0.9	No Car Lift	Fuel Tank Stopper Bracket installation	7 (0.01%)



Estimated Recall Summary Report

Ford Dealer in Chicago Suburb

Date: 10/25/2023

Prospect Radius: 50 mi
 Market Size: 277,881
 12 Mos. Forecast: 69,521

Recall scoring key: 5 = High, 4 = Med, 3 = Low | Recalls excluded: 2 = Remedy not available, 1 = Non-safety related

Please note: The numbers reflected in this report are raw estimates of open recalls in your requested area. Recall Masters reservation system is not applied to this report. After the enrollment process is completed, an updated count report with our reservation system applied is supplied before each campaign execution.

Make	OEM Code	NHTSA Code	Overall Score	Risk Score	Profit Score	Reimb. Labor	Labor Estimate	Service Difficulty	Recall Description	Recall Qty (%)
FORD	08C01	08V096000	4	3	4	\$53	0.5	No Car Lift	Front Drivers Seat Back Inspection And Repair	7 (0.01%)
FORD	01S25	01V261000	4	4	4	\$74	0.7	No Car Lift	Wiper Motor Gear Cover	7 (0.01%)
FORD	00S05	00V073000	4	4	4	\$74	0.7	No Car Lift	Trailer Hitch Attachment	7 (0.01%)
FORD	01S26	01V262000	4	4	2	\$74	0.7	Car Lift	Auxiliary Rear A/C Blower Wiring	7 (0.01%)
FORD	06S45	06V383000	4	4	4	\$106	1.0	No Car Lift	Door Latch Freezing *Cold States*	7 (0.01%)
FORD	08S02	08V057000	4	4	2	\$148	1.4	Car Lift	Fuel Rail Cross Over Hose	7 (0.01%)
FORD	12S29	12V149000	4	4	4	\$64	0.6	No Car Lift	Passenger Side Wiper Motor Electrical Connector Inspection and Repair	7 (0.01%)
FORD	11C18	11V352000	4	4	3	\$32	0.3	No Car Lift	Multifunction Switch Inspection And Replacement	7 (0.01%)
FORD	12S36	12V374000	4	4	3	\$21	0.2	No Car Lift	Wiper Arm May Fail While Driving - Inspect and Replace	7 (0.01%)
FORD	11S17	11V126000	4	4	4	\$64	0.6	No Car Lift	Fuel Line Inspection	7 (0.01%)
FORD	99S09	99V062001	4	4	3	\$21	0.2	No Car Lift	Speed Control Cable	7 (0.01%)
FORD	01S30	01V390000	4	4	2	\$64	0.6	Car Lift	Engine Cooling Fan Circuit Breaker	7 (0.01%)
FORD	03S02	03V196000	4	3	4	\$74	0.7	No Car Lift	Intermediate Steering Shaft	7 (0.01%)
FORD	94S91		4	4	4	\$64	0.6	No Car Lift	Installation of a Parking Brake Lock-in Wedge	7 (0.01%)
FORD	99S34	99V310001	4	3	4	\$127	1.2	No Car Lift	Liftgate Bracket Reinforcement	7 (0.01%)
FORD	00S47	00V402000	4	3	4	\$53	0.5	No Car Lift	Sway Bar Links	7 (0.01%)
FORD	95S28		4	4	4	\$53	0.5	No Car Lift	Ignition Switch Replacement	7 (0.01%)
FORD	15E06		4	4	3	\$32	0.3	Programming Only	Powertrain Control Module Reprogramming	7 (0.01%)
FORD	17C06	17V225000	4	4	2	\$127	1.2	Car Lift	Transmission Park Rod Actuating Plate	7 (0.01%)
FORD	17E06		4	3	4	\$74	0.7	No Car Lift	Crankcase Oil Separator Filter Element	7 (0.01%)
FORD	17B28		4	3	4	\$64	0.6	No Car Lift	Electronic Throttle Body Replacement	7 (0.01%)
FORD	17C09	17V331000	4	4	4	\$64	0.6	No Car Lift	Exterior Door Handle	7 (0.01%)
FORD	19S31	19V688000	4	4	2	\$64	0.6	Car Lift	Passenger Side Rear Axle Shaft Inspection	7 (0.01%)
FORD	20S18	20V197000	4	4	4	\$53	0.5	No Car Lift	Gear Position Display May Be Inaccurate	7 (0.01%)
FORD	20S21	20V263000	4	4	3	\$32	0.3	Programming Only	Instrument Cluster Not In Park Warning Message	7 (0.01%)
FORD	20S56		4	4	2	\$53	0.5	Car Lift	Dana Axle Tube Weld	7 (0.01%)
FORD	21E08		4	3	4	\$53	0.5	Programming Only	Powertrain Control Module Update	7 (0.01%)
FORD	21C24		4	4	3	\$42	0.4	No Car Lift	ISOFIX Child Restraint Rap Cab Rear	7 (0.01%)
FORD	22S24	22V253000	4	3	4	\$106	1.0	No Car Lift	Steering Column Wiring Too Short	7 (0.01%)
FORD	22S08	22V089000	4	4	4	\$148	1.4	No Car Lift	Power Steering Pressure Line May Detach and Leak	7 (0.01%)
FORD	21C19	21V652000	4	4	4	\$53	0.5	No Car Lift	Side Air Bag Weld Stud May Fail	7 (0.01%)
FORD	23E07		4	3	4	\$53	0.5	Programming Only	Software Calibration Update	7 (0.01%)
FORD	22G06		4	2	4	\$117	1.1	No Car Lift	Heated Steering Wheel Performance Upgrade	7 (0.01%)
FORD	17S33	17V652000	3	3	3	\$21	0.2	No Car Lift	Door Latch Replacement	1,154 (1.66%)
FORD	22S02	22V011000	3	3	2	\$106	1.0	Car Lift	Brake Light Malfunction and Possible Rollaway Risk	1,147 (1.65%)
FORD	21S32	21V537000	3	3	2	\$127	1.2	Car Lift	Rear toe link replacement	723 (1.04%)
FORD	22S26	22V250000	3	3	3	\$32	0.3	No Car Lift	Windshield Wipers May Fail	626 (0.9%)
FORD	15S16	15V246000	3	3	3	\$21	0.2	No Car Lift	Door Latch Replacement	417 (0.6%)
FORD	19B37		3	2	2			Programming Only	Powertrain Control Module Reprograming	417 (0.6%)
FORD	21B10		3	3	3	\$32	0.3	Programming Only	Powertrain Control Module (PCM) Reprogram For Cam Phaser Rattle	341 (0.49%)
FORD	19S16	19V362000	3	3	2	\$64	0.6	Car Lift	Unintentional Rollaway Due to Detached Shift Cable	243 (0.35%)



Estimated Recall Summary Report

Ford Dealer in Chicago Suburb

Date: 10/25/2023

Prospect Radius: 50 mi
 Market Size: 277,881
 12 Mos. Forecast: 69,521

Recall scoring key: 5 = High, 4 = Med, 3 = Low | Recalls excluded: 2 = Remedy not available, 1 = Non-safety related

Please note: The numbers reflected in this report are raw estimates of open recalls in your requested area. Recall Masters reservation system is not applied to this report. After the enrollment process is completed, an updated count report with our reservation system applied is supplied before each campaign execution.

Make	OEM Code	NHTSA Code	Overall Score	Risk Score	Profit Score	Reimb. Labor	Labor Estimate	Service Difficulty	Recall Description	Recall Qty (%)
FORD	06R13		3	1	4	\$106	1.0	Programming Only	Door latch may operate in cold weather	188 (0.27%)
FORD	19R02		3	3	2			No Car Lift	Steering Gear Motor Bolt Corrosion	139 (0.2%)
FORD	20E08		3	3	3			No Car Lift	Extended Idle Diesel Particulate Filter Calibration	76 (0.11%)
FORD	22S25	22V254000	3	3	2	\$64	0.6	Car Lift	Transmission Shifter Cable Bushing	70 (0.1%)
FORD	20B53		3	3	3			Car Lift	Fuel Pump Control Module Replacement	63 (0.09%)
FORD	22B28		3	3	3	\$42	0.4	Programming Only	Reprogram HVAC Control Module	63 (0.09%)
FORD	19S19	19V433000	3	3	3	\$32	0.3	Programming Only	Unexpected Transmission Downshift	56 (0.08%)
FORD	23E03		3	3	3	\$42	0.4	Programming Only	Powertrain Control Module Reprogramming	56 (0.08%)
FORD	17B23		3	3	3	\$42	0.4	No Car Lift	Driver Airbag Inflator Replacement	49 (0.07%)
FORD	20B27		3	3	3	\$48	0.5	Programming Only	Powertrain Control Module (PCM) Reprogram	49 (0.07%)
FORD	20E03		3	3	3	\$32	0.3	Programming Only	Anti-Lock Brake Module Reprogram	42 (0.06%)
FORD	14C10	14V710000	3	3	2	\$117	1.1	Car Lift	Seat frame Clearance Adjustment	35 (0.05%)
FORD	19B22		3	3	3			No Car Lift	Battery Junction Box Clean And Seal	35 (0.05%)
FORD	19B12		3	3	3			Programming Only	Anti-Lock Brake System Module Software Update	28 (0.04%)
FORD	19B27		3	3	3			Car Lift	Uncured Power Steering Hoses	28 (0.04%)
FORD	21B05		3	1	4	\$53	0.5	No Car Lift	High Speed Cooling Fan Motor Relay	28 (0.04%)
FORD	14B09	14V802000	3	3	2	\$64	0.6	Car Lift	Driver Airbag Inflator Replacement	21 (0.03%)
FORD	19B05		3	3	3	\$32	0.3	Programming Only	Sudden Transmission Downshift - Powertrain Control Module Reprogramming	21 (0.03%)
FORD	19E04		3	3	3			Programming Only	Powertrain Control Module Reprogramming	21 (0.03%)
FORD	20E01		3	3	3	\$32	0.3	Programming Only	Powertrain Control Module (PCM) Reprogramming	21 (0.03%)
FORD	15E05		3	3	3	\$32	0.3	Programming Only	Power Control Module Reprogramming	14 (0.02%)
FORD	17G01		3	3	2	\$64	0.6	Car Lift	Rear Suspension Toe Link Replacement	14 (0.02%)
FORD	18B21		3	2	3			No Car Lift	Automatic Engine Idle Shutdown	14 (0.02%)
FORD	18E03		3	3	3			Programming Only	Reprogram Powertrain Control Module	14 (0.02%)
FORD	1900		3	3	3			No Car Lift	Powertrain Control Module Reprogramming	14 (0.02%)
FORD	19R01		3	2	3			Car Lift	Rear Suspension Toe Link	14 (0.02%)
FORD	20B23		3	3	2	\$106	1.0	Car Lift	Replacement Of Clutch Actuator Motors	14 (0.02%)
FORD	22B10		3	2	3	\$32	0.3	No Car Lift	Additional Remote Control And Key Blank	14 (0.02%)
FORD	22B48		3	3	3	\$42	0.4	Programming Only	Off-Board Charger Controller Module Programming	14 (0.02%)
FORD	22E02		3	2	3			No Car Lift	Particulate Matter Sensor Installation	14 (0.02%)
FORD	23B50		3	2	3			No Car Lift	Charge Cord Stuck	14 (0.02%)
FORD	00S45	00V394000	3	3	1	\$32	0.3	Car Lift	Hood Latch Striker	7 (0.01%)
FORD	07E19		3	3	3	\$42	0.4	No Car Lift	Powertrain Control Module (PCM) Recalibration	7 (0.01%)
FORD	00E11		3	3	3			No Car Lift	On-Board Diagnostic System	7 (0.01%)
FORD	16C12	16V617000	3	3	3	\$32	0.3	No Car Lift	Power Window Configuration	7 (0.01%)
FORD	17E01		3	3	3	\$32	0.3	Programming Only	Powertrain Control Module Reprogramming	7 (0.01%)
FORD	17B38		3	3	3			Programming Only	Powertrain Control Module Reprogramming	7 (0.01%)
FORD	17E08		3	3	3			Programming Only	Powertrain Control Module Reprogramming	7 (0.01%)
FORD	17B30		3	3	3			No Car Lift	Camshaft Roller Follower Replacement	7 (0.01%)
FORD	19B03		3	2	3			Car Lift	Exhaust Gas Re-circulation Temperature Sensor Replacement	7 (0.01%)
FORD	19B11		3	3	3			No Car Lift	Headlamp Control Module Reprogram	7 (0.01%)



Estimated Recall Summary Report

Ford Dealer in Chicago Suburb

Date: 10/25/2023

Prospect Radius: 50 mi
 Market Size: 277,881
 12 Mos. Forecast: 69,521

Recall scoring key: 5 = High, 4 = Med, 3 = Low | Recalls excluded: 2 = Remedy not available, 1 = Non-safety related

Please note: The numbers reflected in this report are raw estimates of open recalls in your requested area. Recall Masters reservation system is not applied to this report. After the enrollment process is completed, an updated count report with our reservation system applied is supplied before each campaign execution.

Make	OEM Code	NHTSA Code	Overall Score	Risk Score	Profit Score	Reimb. Labor	Labor Estimate	Service Difficulty	Recall Description	Recall Qty (%)
FORD	14000		3	3	3			Programming Only	Powertrain Control Module Reprogramming	7 (0.01%)
FORD	20B31		3	3	3	\$32	0.3	Programming Only	Standard Battery Guard Feature Timeout	7 (0.01%)
FORD	21B08		3	3	3			Programming Only	Heated Mirror And Integrated Trailer Relay Module (ITRM) Reflash	7 (0.01%)
FORD	21B32		3	3	3	\$32	0.3	No Car Lift	Trailer Perimeter Alarm	7 (0.01%)
FORD	21B71		3	3	3	\$32	0.3	No Car Lift	Driver Airbag Module Replacement	7 (0.01%)
FORD	22E11		3	3	3	\$32	0.3	Programming Only	Powertrain Control Module (PCM) Reprogramming	7 (0.01%)
FORD	23G01		3	2	3	\$11	0.1	No Car Lift	Missing Floor Mats	7 (0.01%)
FORD	23S12	23V162000	2	5	2	\$106	1.0	Car Lift	Front Brake Hoses May Rupture	987 (1.42%)
FORD	22S71	22V842000	2	4	4	\$74	0.7	No Car Lift	Windshield Wiper Motor May Fail	501 (0.72%)
FORD	22S51	22V644000	2	4	3	\$21	0.2	No Car Lift	Cloudy Camera Lens May Reduce Rear Visibility	348 (0.5%)
FORD	23S10	23V163000	2	4	3	\$32	0.3	No Car Lift	Windshield Wipers May Fail	174 (0.25%)
FORD	23C16	23V358000	2	3	3			No Car Lift	Seat Belt Latch Plate Access	153 (0.22%)
FORD	22S35	22V337000	2	5	3			No Car Lift	Driver's Air Bag May Not Deploy	146 (0.21%)
FORD	23S27	23V380000	2	5	3			No Car Lift	Under Hood Fire	139 (0.2%)
FORD	23S08	23V306000	2	4	4	\$53	0.5	No Car Lift	Replacement Air Bag Inflator Incorrectly Installed	76 (0.11%)
FORD	23S23	23V342000	2	3	3			Programming Only	Rear 360 Camera Blue Screen	70 (0.1%)
FORD	23S10	23V163000	2	4	3	\$32	0.3	No Car Lift	Both Front Wiper Arm Inspection	42 (0.06%)
FORD	23S36	23V502000	2	4	3			No Car Lift	Front Door Latch Pawl May Crack	35 (0.05%)
FORD	23E01		2	1	3			No Car Lift	2020-22 3.0L6.7L DIESEL NOX SENSORS MISSING PREHEAT	28 (0.04%)
FORD	23S55	23V675000	2	4	3			Car Lift	Vehicle Rollover From Driveshaft Disconnect	28 (0.04%)
FORD	22S74	22V880000	2	4	3			Car Lift	Driveshaft Replacement	21 (0.03%)
FORD	22B34		2	3	2	\$106	1.0	Car Lift	Rear Axle Half-Shaft and Hub Assembly Replacement	21 (0.03%)
FORD	23S30	23V418000	2	4	3			No Car Lift	Rear Lightbar Replacement	21 (0.03%)
FORD	23S33	23V440000	2	5	3			No Car Lift	PHEV Battery Cell Degradation	21 (0.03%)
FORD	23C25	23V506000	2	4	3			No Car Lift	Instrument Panel May Fail To Illuminate	21 (0.03%)
FORD	23S48		2	4	3			No Car Lift	Replace Rear View Camera	21 (0.03%)
FORD	23S55	AWAITING ID	2	5	5	\$329	3.1	Programming Only	REAR AXLE BOLT FRACTURES	21 (0.03%)
FORD	23C24	23V510000	2	4	3			No Car Lift	SDLC Module Waterlogged During Engine Rework	14 (0.02%)
FORD	23S49	23V595000	2	4	2	\$53	0.5	Car Lift	Left Rear Axle Shaft May Break	14 (0.02%)
FORD	23B52		2	4	4	\$53	0.5	No Car Lift	Incorrect Lug Wrench	14 (0.02%)
FORD	22S62	22V731000	2	3	5	\$159	1.5	Car Lift	Loose Rear Stabilizer Bar Bracket Bolts	7 (0.01%)
FORD	23S12	23V162000	2	4	2	\$138	1.3	Car Lift	Front Brake Flexible Hose Replacement	7 (0.01%)
FORD	23S33		2	5	3			No Car Lift	PHEV Battery Cell Degradation	7 (0.01%)
FORD	23S28	23V378000	2	5	4	\$53	0.5	No Car Lift	Risk of Underhood Fire " Park Vehicle Outdoors	7 (0.01%)
FORD	23S36	23V502000	2	4	3			No Car Lift	Left And Right Front Door Latch Replacement	7 (0.01%)
FORD	23S46	23V573000	2	4	4	\$106	1.0	Programming Only	Incorrect Rearview Camera Image May Display	7 (0.01%)
FORD	23S56		2	4	3			No Car Lift	High Voltage Battery Junction Box Replacement	7 (0.01%)
FORD	21R01		1	1	3			Car Lift	Rear Toe Link Replacement	591 (0.85%)
FORD	22N18		1	1	3			No Car Lift	Replacement Of High-Pressure Fuel Injectors	334 (0.48%)
FORD	22N02		1	1	3			Car Lift	Front Brake Flexible Hose Replacement	285 (0.41%)
FORD	09L02		1	1	3	\$11	0.1	Programming Only	Customer Maintenance Reminder Vehicle Shimmy And Tire Inflation Pressure	216 (0.31%)



Estimated Recall Summary Report

Ford Dealer in Chicago Suburb

Date: 10/25/2023

Prospect Radius: 50 mi
 Market Size: 277,881
 12 Mos. Forecast: 69,521

Recall scoring key: 5 = High, 4 = Med, 3 = Low | Recalls excluded: 2 = Remedy not available, 1 = Non-safety related

Please note: The numbers reflected in this report are raw estimates of open recalls in your requested area. Recall Masters reservation system is not applied to this report. After the enrollment process is completed, an updated count report with our reservation system applied is supplied before each campaign execution.

Make	OEM Code	NHTSA Code	Overall Score	Risk Score	Profit Score	Reimb. Labor	Labor Estimate	Service Difficulty	Recall Description	Recall Qty (%)
FORD	22E04		1	1	3			Programming Only	Reprogram Powertrain Control Module (PCM) and Transmission Control Module (TCM)	195 (0.28%)
FORD	22L05		1	2	3	\$21	0.2	Programming Only	Vehicle Emissions Control Information Label Update	174 (0.25%)
FORD	21R02		1	1	3			Car Lift	Rear Toe Link Inspection Replacement	104 (0.15%)
FORD	21C31	21V922000	1	3	3			Programming Only	FRONT BRAKE PAD REPLACEMENT	76 (0.11%)
FORD	23L02		1	1	3			Programming Only	Passenger Airbag Deactivation Switch Instructions Not In Owner's Manual	63 (0.09%)
FORD	22G04		1	1	3	\$48	0.5	Programming Only	Hybrid Battery Reduced Electric Vehicle Operation	56 (0.08%)
FORD	23C20	23V420000	1	4	3			Programming Only	Head Restraint Owners Manual Addendum	49 (0.07%)
FORD	14L04		1	1	3	\$11	0.1	Programming Only	Vehicle Emission Control Information (VECI) Label Replacement	28 (0.04%)
FORD	22G05		1	1	3			Programming Only	2022 F150 AND SUPER DUTY MISSING BADGES	28 (0.04%)
FORD	20L02		1	1	3			Programming Only	Owner's Manual Engine Idle Shutdown Callout Missing	21 (0.03%)
FORD	20L03		1	1	3			Programming Only	Owner's Manual Engine Idle Shutdown Callout Missing	14 (0.02%)
FORD	21S06	21V087000	1	3	3	\$32	0.3	Programming Only	Replacement Of Safety Certification Label	14 (0.02%)
FORD	21C22	21V711000	1	3	3			Programming Only	WINDSHIELD GLASS RESEAL	14 (0.02%)
FORD	21B68		1	3	3			Programming Only	TMAP SENSOR ICING	14 (0.02%)
FORD	23C20	23V420000	1	4	3	\$21	0.2	Programming Only	Head Restraint Owners Manual Addendum	14 (0.02%)
FORD	03E04		1	2	1			Programming Only	Non-California Certified Vehicles	7 (0.01%)
FORD	97S88		1	1	1			No Car Lift	Hood Separation	7 (0.01%)
FORD	16E04		1	1	3	\$11	0.1	Programming Only	Fuel Filler Pipe Label Correction	7 (0.01%)
FORD	18L06		1	1	3			Programming Only	Raptor Supplement Auxiliary Switch Owners Manual Update	7 (0.01%)
FORD	23C18	23V379000	1	3	3			Programming Only	Install New Tread Label	7 (0.01%)
FORD	22N01		0	3	3			Programming Only	REAR WHEEL KNUCKLE REPLACEMENT	348 (0.5%)
FORD	15B22		0	3	3			Programming Only	Transmission Control Module Reprogramming	278 (0.4%)
FORD	21B11		0	2	5	\$307	2.9	No Car Lift	Second Row Inflatable Seat Belt	118 (0.17%)
FORD	21B04		0	3	5	\$329	3.1	No Car Lift	Frame Rail Crack	63 (0.09%)
FORD	21B09		0	3	5	\$201	1.9	No Car Lift	3G TO 4G MODEM	35 (0.05%)
FORD	16B23		0	3	3			No Car Lift	Electronic Throttle Body Replacement	21 (0.03%)
FORD	22B08		0	1	4	\$127	1.2	Programming Only	Electronic Control Module Recovery	14 (0.02%)
FORD	13B17		0	3	3	\$32	0.3	No Car Lift	Throttle Body PYM Calibration Update	7 (0.01%)
FORD	02B02		0	3	4	\$64	0.6	Programming Only	Optional Cvpi Upgrade program	7 (0.01%)
FORD	00S20	00V218000	0	4	4	\$64	0.6	No Car Lift	A-Pillar Trim	7 (0.01%)
FORD	16B32		0	3	3			No Car Lift	Electronic Throttle Body Repair	7 (0.01%)
FORD	18 IF YOU		0	2	3			No Car Lift	Front Seatbelt Pretensioners	7 (0.01%)
FORD	20S31		0	4	3			Car Lift	Brake Master Cylinder	7 (0.01%)
FORD	21B03		0	3	5	\$1,092	10.3	Car Lift	Number One Planetary And Ring Gear Assembly	7 (0.01%)